



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0706/2020/NS
DATE	:	29-Sep-20
WIP	:	51112

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR NEVAJ KOCHHAR
ADDRESS	:	2 PANDAN VALLEY #06-205 SINGAPORE 597626
TELEPHONE	:	HP +65 91431914
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1900080709
VEHICLE NO	:	SMK 2170 S
MODEL CODE	:	AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR	:	29/3/2019
ENGINE NO	:	CHZ C27230
CHASSIS NO	:	WAUZZZ8VXK1022681
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	26-Sep-20
PLACE OF ACCIDENT	:	PANDAN VALLEY CARPARK



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 2170 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 280.00 ✓	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00 X	
3	TO RENEW REAR WINDSCREEN AND RHS REAR 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$ 600.00 ✓	✓
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND RHS REAR 1/4 GLASS.	S/N \$ 400.00 ✓	✓
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00 150	✓
6	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 2,040.00</u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 2170 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00	✓
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	✓
9	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	3000 ✓
10	TO RESPRAY REAR BUMPER, RHS REAR DOOR, RHS REAR FENDER, DOOR ENTRANCES, RHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENTS AND JOINT SEALER WORKS.	\$ 4,125.00	3025 55 x 500 = 2025 ✓
11	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL	S/N \$ 280.00	✓
12	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>13,637.00</u>	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 2170 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 REAR BUMPER <i>Repair</i>	S	1,944.00 X	
2 REAR BUMPER FIXING PARTS <i>Not in</i>	S	191.00 X	
3 REAR BUMPER SPOILER <i>Not in</i>	S	234.00 X	
4 REAR BUMPER GUIDE SECTION - RH <i>Not in</i>	S	16.00 X	
5 REAR LIGHT REFLECTOR - RH	S	41.00 X	
6 REAR BUMPER GUIDE SECTION - RH <i>Not in</i>	S	66.00 X	
7 REAR FENDER - RH <i>Detached</i>	S	2,305.00 X	1844
8 REAR WINDSCREEN <i>Not in</i>	S	805.00 X	643.60
9 SIDE WINDOW - RH	S	563.00 X	450.40
10 PRIMER <i>Not in</i>	S	19.00 X	14.96
11 WHEEL HOUSING LINER - RH <i>Not in</i>	S	237.00 X	
12 WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not in</i>	S	88.00 X	
13 REAR DOOR - RH <i>Distorted</i>	S	2,494.00 X	1995.20
14 REAR DOOR OUTER SEAL <i>Not in</i>	NEC S	159.00 X	126.80
15 BONDING AGENT <i>Not in</i>	NEC S	47.00 X	
16 CLEANING SOLUTION <i>Not in</i>	NEC S	65.00 X	
17 REAR DOOR ATTACHMENT PARTS <i>Not in</i>	S	127.00 X	
18 REAR DOOR CATCH <i>Not in</i>	S	93.00 X	
19 REAR DOOR INNER SEAL <i>Not in</i>	S	189.00 X	
20 REAR ALUMINIUM RIM - RH <i>Not in</i>	S	699.00 X	558.80
SUB TOTAL SPARE PARTS	:	\$ 10,382.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 2170 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/N	NETT	
21 REAR WHEEL SPOILER - RH <i>Yes</i>	1		35.00	✓ 27.36
22 REAR WINDSCREEN SEALANT	S/N	S	200.00	✓ 200
23 1/4 GLASS SEALANT <i>Yes</i>	S/N	S	100.00	✓ 100
24 METAL FILLER POWDER	S/N	S	280.00	✓ 280
25 STONE CHIP	S/N	S	180.00	✓ 180
26 CAVITY WAX <i>Yes</i>	S/N	S	140.00	✓ 140
27 ACRYLIC SEALANT	S/N	S	180.00	✓ 180
28 REAR NO PLATE <i>Not in</i>	S/N	S	60.00	✓
29 SUNDRIES <i>NEC</i>		S	350.00	✓ 15.68
TOTAL SPARE PARTS	:	\$	11,907.00	
TOTAL LABOUR CHARGES	:	\$	13,637.00	
GRAND TOTAL	:	\$	25,544.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adam
SURVEYED DATE : 30/04/20
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : All Authorised, 13 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0706/2020/NS
DATE : 29-Sep-20
WIP : 51112

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

13 days - ok - Jy - 17 Dec 20

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR NEVAJ KOCHHAR
ADDRESS : 2 PANDAN VALLEY
#06-205
SINGAPORE 597626
TELEPHONE : HP +65 91431914
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900080709
VEHICLE NO : SMK 2170 S
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 29/03/2019
ENGINE NO : CHZ C27230
CHASSIS NO : WAUZZZ8VXK1022681
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Sep-20
PLACE OF ACCIDENT : PANDAN VALLEY CARPARK



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 2170 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N	\$ 280.00	\$	280.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N	\$ 280.00		
3	TO RENEW REAR WINDSCREEN AND RHS REAR 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N	\$ 600.00	\$	600.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND RHS REAR 1/4 GLASS.	S/N	\$ 400.00	\$	400.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N	\$ 200.00	\$	150.00
6	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N	\$ 280.00	\$	280.00
TOTAL LABOUR CHARGES		:	\$ 2,040.00	\$	1,710.00

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 2170 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 1,710.00
7	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00	\$ 1,400.00
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	\$ 1,400.00
9	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	\$ 3,000.00
10	TO RESPRAY REAR BUMPER, RHS REAR DOOR, RHS REAR FENDER, DOOR ENTRANCES, RHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENTS AND JOINT SEALER WORKS.	\$ 4,125.00	\$ 3,025.00
11	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL	S/N \$ 280.00	\$ 280.00
12	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 13,637.00	\$ 11,007.00



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 2170 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR BUMPER	\$	1,944.00	
2 REAR BUMPER FIXING PARTS	\$	191.00	
3 REAR BUMPER SPOILER	\$	234.00	
4 REAR BUMPER GUIDE SECTION - RH	\$	16.00	
5 REAR LIGHT REFLECTOR - RH	\$	41.00	
6 REAR BUMPER GUIDE SECTION - RH	\$	66.00	
7 REAR FENDER - RH	\$	2,305.00	\$ 1,844.00
8 REAR WINDSCREEN	\$	805.00	\$ 643.60
9 SIDE WINDOW - RH	\$	563.00	\$ 450.40
10 PRIMER	\$	19.00	\$ 14.96
11 WHEEL HOUSING LINER - RH	\$	237.00	
12 WHEEL HOUSING LINER ATTACHMENT PARTS	\$	88.00	
13 REAR DOOR - RH	\$	2,494.00	\$ 1,995.20
14 REAR DOOR OUTER SEAL	NEC \$	159.00	\$ 126.80
15 BONDING AGENT	NEC \$	47.00	
16 CLEANING SOLUTION	NEC \$	65.00	
17 REAR DOOR ATTACHMENT PARTS	\$	127.00	
18 REAR DOOR CATCH	\$	93.00	
19 REAR DOOR INNER SEAL	\$	189.00	
20 REAR ALUMINIUM RIM - RH	\$	699.00	\$ 558.80
SUB TOTAL SPARE PARTS	:	\$ 10,382.00	\$ 5,633.76



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 2170 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
	c/f		\$	5,633.76
21 REAR WHEEL SPOILER - RH	\$	35.00	\$	27.36
22 REAR WINDSCREEN SEALANT	S/N \$	200.00	\$	200.00
23 1/4 GLASS SEALANT	S/N \$	100.00	\$	100.00
24 METAL FILLER POWDER	S/N \$	280.00	\$	280.00
25 STONE CHIP	S/N \$	180.00	\$	180.00
26 CAVITY WAX	S/N \$	140.00	\$	140.00
27 ACRYLIC SEALANT	S/N \$	180.00	\$	180.00
28 REAR NO PLATE	S/N \$	60.00		
29 SUNDRIES	\$	350.00	\$	15.68
TOTAL SPARE PARTS	:	\$ 11,907.00	\$	6,756.80
TOTAL LABOUR CHARGES	:	\$ 13,637.00	\$	11,007.00
GRAND TOTAL	:	\$ 25,544.00	\$	17,763.80

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-09/12/20