

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Sep 2020		30 Sep 2020 16:13	S\$4,100.00 Edit Estimates	S\$4,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	Performance Motors Limited , Co. Reg. No.: 197401559W, GST No.: M20020081X	
Main Claimant:	Tan Hua Oo , ID: S1435242B	
Vehicle Reg. No.:	SGH1826C	Date of Loss: 30/09/2020 08:00 - :59 [53 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 629284	Policy/Cover Note No.: 29136949MCY (Comprehensive) Coverage: 01/10/2019 - 30/09/2020
Vehicle Reg. No. (Insured):	SMU278B	Policy No. (Claimant): Excess:
Repairer:	Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB, 417800 Kaki Bukit - Tel: 97489940	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 30/10/2020]	
Adj Asg. Remarks:	on WP. Liab: NR. Agree on SJE. Assign: LKK - Marcus Chua. Contact: 9748 9940	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGH1826C (629284)**
[SMU278B]
TP
Tan Hua Oo
Sep 30 2020 8:00AM
[Performance Motors Limited]
Imperium Automotive - Kaki Bukit

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/10/20 17:07	Adjuster Immediate Advice	Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/10/20 17:27	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	01/10/20 17:28	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
4	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
5	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
6	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
7	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
8	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
9	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
10	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
11	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
12	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
13	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
14	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
15	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
16	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
17	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
18	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
19	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
20	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
21	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
22	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
23	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
24	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
25	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
26	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
27	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
28	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
29	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
30	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
31	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
32	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
33	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
34	01/10/20 17:28	General View	Load JPG	<input checked="" type="checkbox"/>
35	01/10/20 17:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	01/10/20 17:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	01/10/20 17:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
39	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
40	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
41	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
42	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
43	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
44	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
45	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
46	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
47	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
48	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
49	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
50	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
51	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
52	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
53	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
54	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
55	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
56	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
57	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
58	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
59	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
60	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
61	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
62	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
63	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
64	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
65	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
66	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
67	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
68	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
69	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
70	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
71	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
72	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
73	01/10/20 17:29	Reinspection Photo		<input checked="" type="checkbox"/>
74	05/10/20 16:47	After Repair Photo		<input checked="" type="checkbox"/>
75	05/10/20 16:47	After Repair Photo		<input checked="" type="checkbox"/>
76	05/10/20 16:47	After Repair Photo		<input checked="" type="checkbox"/>
77	05/10/20 16:47	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/09/20 13:44	Email forward by Winnie Chua - PRI from JusEquity Law Corporation		<input checked="" type="checkbox"/>
2	30/09/20 13:44	TP SGH1826C Gia Report		<input checked="" type="checkbox"/>
3	30/09/20 15:34	Agree on SJE		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	30/09/20 16:11	Email - Outsource Instruction		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG20010499/UQF3S2**Date:** 06/10/2020REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29136949MCY
Claimant Vehicle No :	SGH1826C	Insured Vehicle No :	SMU278B
Date of Loss:	30/09/2020	Nature of Claim:	TP
		Claim No:	629284

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGH1826C	Engine No:	1ZRY238828
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104542971
Reg. Date:	27/04/2016 (Man. Year: 2015)	Odometer:	93623 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,224.73	3,114.37	6,110.36	66.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,400.00	2,030.00	2,370.00	53.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,624.73	5,144.37	8,480.36	62.24
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	13,624.73	4,100.00	9,524.73	69.91

INSPECTION

Date of Assignment:	30/09/2020		
Date Inspected:	01/10/2020	Inspected At:	Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB Singapore 417800
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Oct 2020)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGH1826C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	884.30 FL	*- FL
2	1		*BOOTLID LOGO	Necessary	85.50 FL	*68.50 FL
3	1		*BOOTLID EMBLEM COROLLA	Necessary	68.00 FL	*56.80 FL
4	1		*BOOTLID EMBLEM ALTIS	Necessary	65.37 FL	*52.20 FL
5	2		*BOOTLID HINGE	Not Necessary	371.20 FL	*- FL
6	1		*BOOTLID OUTER CHROME GARNISH	Not Necessary	482.60 FL	*- FL
7	1		*BOOTLID LAMP	Not Necessary	970.60 FL	*- FL
8	1		*BOOTLID INNER LOCK	Not Necessary	253.00 FL	*- FL
9	1		*BOOTLID STRIKER	Not Necessary	65.00 FL	*- FL
10	1		*BOOTLID INNER TRIM BOARD	Not Necessary	352.80 FL	*- FL
11	1		*BOOTLID WEATHERSTRIP	Twisted	285.60 FL	*285.60 FL
12	1		*BOOTLID ANTENNA SENSOR	Shorted	385.20 FL	*385.20 FL
13	1		*REVERSE CAMERA	Not Necessary	425.80 FL	*- FL
14	1		*REAR BUMPER	Deformed	784.60 FL	*588.20 FL
15	1		*REAR BUMPER REINFORCEMENT	Dented	487.30 FL	*392.60 FL
16	2		*REAR BUMPER SIDE RETAINER	Not Necessary	204.00 FL	*- FL
17	2		*REAR BUMPER BRACKET	Not Necessary	171.20 FL	*- FL
18	1		*REAR BUMPER CARRIER	No such part	97.00 FL	*- FL
19	1		*REAR BUMPER REFLECTOR	N/s Cracked	315.60 FL	*65.50 FL
20	1		*REAR END PANEL	Badly Dented	672.60 FL	*600.10 FL
21	1		*REAR END PANEL TOP GARNISH	Twisted	146.00 FL	*146.00 FL
22	1		*TAILLAMP	N/s Cracked	1,189.20 FL	*594.60 FL
23	2		*TAILLAMP LOWER BRACKET	Not Necessary	164.00 FL	*- FL
24	1		*REAR FLOOR PANEL TOP BOARD	Torn	517.20 FL	*517.20 FL
25	1		*EXHAUST PIPE	Repair	786.30 FL	*- FL
26	1		*EXHAUST MOUNTING	Not Necessary	137.20 FL	*- FL
27	1		*EXHAUST HEAT SHIELD	Not Necessary	145.80 FL	*- FL
28	1		*REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
29	1		*BOOTLID SEALANT	Not Necessary	100.00 FS	*- FS
30	1		*BOOTLID LAMP SEAL	Not Necessary	100.00 FS	*- FS
31	1		*BOOTLID LAMP CLIPS	Not Necessary	100.00 FS	*- FS
32	1		*BOOTLID OUTER CHROME GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
33	1		*BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
35	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
36	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*TAILLAMP SEAL	Not Necessary	160.00 FS	*- FS
38	1		*TAILLAMP CLIPS	Not Necessary	100.00 FS	*- FS
39	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	100.00 FS	*- FS
40	1		*REAR NO PLATE W/CASING	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,852.97	4,052.50
- List Item Discount on L Items 25.00/25.00% (\$)	2,628.24	938.13
Total Parts (\$)	9,224.73	3,114.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT BOOTLID COMPONENT.	New	150.00	0.00
2	REMOVE & REPLACE REVERSE SENSOR.	New	150.00	50.00
3	REMOVE & REFIT EXHAUST PIPE.	New	150.00	60.00
4	DIAGNOSTIC RESET FAULT CODE.	New	300.00	0.00
5	CHECK WIRING.	New	150.00	30.00
6	PANEL BEAT ON ACCIDENT AREA & REPLACED PARTS.	New	1,500.00	800.00
7	TO REMOVE & REFIT UPHOLSTERY.	New	300.00	80.00
8	RUST PROOFING.	New	200.00	30.00
9	SPRAY PAINTING OF ACCIDENT AREA.	New	1,500.00	980.00
			Gross Labour Cost (S\$)	4,400.00
				2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >