

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 05 Oct 2020

**Preliminary Advice**

Insured Vehicle No	: SMU278B	Accident Date	: 30/09/2020
TP Vehicle No	: SGH1826C	Assignment Date	: 30/09/2020
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 5
Date of Inspection	: 01/10/2020		
Inspection At	: IMPERIUM AUTOMOTIVE - KAKI BUKIT (HQ) 25 KAKI BUKIT ROAD 4, #01-49 SYNERGY@KB SINGAPORE 417800		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,624.73
Revised Amount	:S\$	5,144.38
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,144.38
 Lump Sum Repair	:S\$	 4,100.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- The vehicle is economical for repair  
 The vehicle is not economical for repair  
 Part-by-Part repair  
 Lump Sum repair  
  
 The above survey was conducted on a 'without prejudice' basis.