

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTKB/TP/2009/010
Policy No:	B29126381MCX	Date of Loss:	27/09/2020
Vehicle Reg. No.:	SML6925A	Driveable?	yes
Driver Age:	0000-00-00	Third Party Vehicle No.:	SHC7180G
Any Injuries?	no	Contact No:	
Insured/Claimant:	ADVANCE LIMO & RENTAL PTE LTD	Driver:	KOH WEE TECK

Make/Model:	Honda, Freed - GB31	Vehicle Reg. Date:	30 May 2019
Vehicle Colour:	Silver	Engine Number:	LEB5616503
Chassis No:	GB71080201	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	8

Description of Accident/loss REFER TO GIA REPORT

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	6,464.96
Miscellaneous Items	1,800.40
Labour	1,330.00
Paintwork Labour	1,350.00
Towing	0.00
Gross Total(S\$):	10,945.36
GST 7.00%(S\$):	766.18
Nett Amount(S\$):	11,711.54

This claim is handled by: may chai

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT BUMPER	1,050.40	-20.00	840.32
2	1	FRONT FENDER LH	440.20	-20.00	352.16
3	1	FRONT FENDER EMBLEM LH	65.90	-20.00	52.72
4	1	FRONT DOOR LH	950.40	-20.00	760.32
5	1	FRONT DOOR INNER BOARD LH	680.40	-20.00	544.32
6	1	FRONT DOOR LOCK LH	262.40	-20.00	209.92
7	1	FRONT DOOR SIDE MIRROR LH	580.40	-20.00	464.32
8	1	FRONT DOOR SIDE MIRROR COVER LH	98.20	-20.00	78.56
9	1	FRONT DOOR SIDE MIRROR SIGNAL LAMP LH	330.50	-20.00	264.40
10	1	FRONT DOOR HINGE TOP	59.40	-20.00	47.52
11	1	FRONT DOOR HINGE BOTTOM	59.40	-20.00	47.52
12	1	REAR DOOR LH	985.40	-20.00	788.32
13	1	REAR DOOR INNER BOARD LH	680.40	-20.00	544.32
14	1	REAR FENDER LH	912.40	-20.00	729.92
15	1	REAR BUMPER	925.40	-20.00	740.32

Total Parts (\$\$) **6,464.96**

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT WHEEL RIM LH	400.00	0.00	400.00
2	1	REAR WHEEL RIM LH	400.00	0.00	400.00
3	1	FRONT TYRE LH	300.00	0.00	300.00
4	1	REAR TYRE LH	300.00	0.00	300.00
5	10	FRONT DOOR INNER BOARD CLIPS	50.00	0.00	50.00
6	10	REAR DOOR INNER BOARD CLIPS	50.00	0.00	50.00
7	1	FRONT LH WHEEL COVER	150.20	0.00	150.20
8	1	REAR LH WHEEL COVER	150.20	0.00	150.20

Sub Total (\$\$) **1,800.40**

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Dismantle and Refit Rear Fender Glass.	60.00	0.00	60.00
2	1	To Dismantle and Refit Sliding Door Glass.	100.00	0.00	100.00
3	1	To Transfer Sliding Door.	80.00	0.00	80.00
4	1	To Transfer Door.	80.00	0.00	80.00
5	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	100.00	0.00	100.00
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	850.00	0.00	850.00
7	1	To Dismantle and Refit Front Fender Glass.	60.00	0.00	60.00

Gross Labour Cost (\$\$) **1,330.00**

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Supply Spray Terostat Sealant On The Cutting Areas.	50.00	0.00	50.00
2	1	To Carry-Out Body Cavity Preservation.	100.00	0.00	100.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,200.00	0.00	1,200.00

Gross Labour Cost (S\$) 1,350.00

< END OF ESTIMATES >