

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

DANNY SOH YEE LENG
2 ARDMORE PARK #15-04
SINGAPORE 259947

Contact : 93632650, 82227080

ESTIMATE

Repair Code : CLM15039

Date in : 30/09/2020

Vehicle Num. : SLT751T

Model : MITSUBISHI ATTRAGE 1.2 CVT

Chassis/Eng# : MMBSTA13AJH000497/3A92UGK5658

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Dislud</i>	1	828.00	✓ 828.00
REAR BOOTLID 'ATTRAGE' EMBLEM	1	38.00	✓ 38.00
REAR BOOTLID 'C&C' EMBLEM	1	68.00	✓ 68.00
REAR BOOTLID 'LOGO' EMBLEM	1	50.00	✓ 50.00
REAR BOOTLID 'MIVEC' EMBLEM	1	40.00	✓ 40.00
REAR BOOTLID HINGES L/R <i>Best</i>	2	192.00	✓ 384.00
REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R <i>New</i>	4	12.50	+ 50.00
REAR BOOTLID LOCK STRIKER <i>New</i>	1	65.00	+ 65.00
REAR BOOTLID MECHANISM LOCK <i>Dangd</i>	1	206.00	✓ 206.00
REAR BOOTLID NUMBER PLATE LAMP L/R <i>New</i>	2	48.00	+ 96.00
REAR BOOTLID OUTER CHROME HANDLE <i>could</i>	1	318.00	✓ 318.00
REAR BOOTLID OUTER LOCK BUTTON SWITCH <i>2nd</i>	1	80.00	✓ 80.00
REAR BOOTLID WEATHER STRIP <i>at</i>	1	148.00	✓ 148.00
REAR BUMPER <i>Dislud</i>	1	708.00	✓ 708.00
REAR BUMPER SIDE RETAINER L/R <i>me</i>	2	36.00	✓ 72.00
REAR END PANEL <i>Dented</i>	1	402.00	✓ 402.00
REAR END PANEL ANTENNA SENSOR <i>Dangd</i>	1	89.00	✓ 89.00
REAR END PANEL BUZZER SENSOR <i>Dangd</i>	1	84.00	✓ 84.00

*** This is a computer-generated document which requires no signature.***

page 1

3pc Rear bumper reflector 1/2 * 49.00 x 2 = \$ 98.00 ✓
Crashd

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

DANNY SOH YEE LENG
2 ARDMORE PARK #15-04
SINGAPORE 259947

Contact : 93632650, 82227080

ESTIMATE

Repair Code : CLM15039

Date in : 30/09/2020

Vehicle Num. : SLT751T

Model : MITSUBISHI ATTRAGE 1.2 CVT

Chassis/Eng# : MMBSTA13AJH000497/3A92UGK5658

REAR END PANEL INNER AIR VENT	3 Del'd.	1	27.00	✓	27.00
REAR END PANEL INNER AIR VENT GARNISH		1	36.00	✓	36.00
REAR END PANEL INNER TOP GARNISH	Del'd	1	62.00	✓	62.00
REAR END PANEL SIDE GUIDE GARNISH L/R	Del'd could	2	96.00	✓	192.00
REAR EXHAUST GASKET		1	26.00	+	26.00
REAR EXHAUST RUBBER MOUNTING	2 new	2	25.00	+	50.00
REAR EXHAUST SILENCER BOX		1	535.00	+	535.00
REAR FENDER INNER SHIELD L/R	torn	2	45.00	✓	90.00
REAR FENDER INNER TRIM L/R	torn.	2	195.00	✓	390.00
REAR FENDER L/R	Buckled	2	958.00	✓	1916.00
REAR FLOOR PANEL	Rips	1	906.00	+	906.00
REAR FLOOR PANEL CARPET	new	1	249.00	+	249.00
REAR FLOOR PANEL TOP BOARD COVER	torn	1	335.00	✓	335.00
REAR FLOOR TOW HOOK PANEL	Rips	1	209.00	+	209.00
REAR LH FENDER PETROL LID	new	1	68.70	+	68.70
REAR TAILLAMP INNER PANEL L/R	Buckled	2	95.00	✓	190.00
REAR TAILLAMP L/R	could	2	276.00	✓	552.00
REAR WINDSCREEN	lit	1	514.00	✓	514.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

DANNY SOH YEE LENG
2 ARDMORE PARK #15-04
SINGAPORE 259947

Contact : 93632650, 82227080

ESTIMATE

Repair Code : CLM15039

Date in : 30/09/2020

Vehicle Num. : SLT751T

Model : MITSUBISHI ATTRAGE 1.2 CVT

Chassis/Eng# : MMBSTA13AJH000497/3A92UGK5658

		Subtotal before discount	10,073.70
Percentage discount 10%	7687		1,007.37
	6918.30	Sub-total 1	9,066.33
REAR BOOTLID CAMERA <i>Del'd</i>	1	800.00	800.00
REAR BOOTLID NUMBER PLATE <i>3 set</i>	1	25.00	25.00
REAR BOOTLID NUMBER PLATE HOLDER <i>Del'd</i>	1	50.00	50.00
REAR BOOTLID OUTER CHROME HANDLE CLIPS - SET <i>Ne</i>	1	50.00	50.00
REAR BOOTLID TOP SPOILER <i>Del'd</i>	1	850.00	850.00
REAR BUMPER CLIPS - SET <i>Ne</i>	1	80.00	80.00
REAR BUMPER REVERSE SENSOR - SET <i>Del'd</i>	1	350.00	350.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>Ne</i>	1	50.00	50.00
REAR FENDER INNER SHIELD CLIPS L/R - SET <i>Ne</i>	2	30.00	60.00
REAR FENDER INNER TRIM CLIPS L/R - SET <i>Ne</i>	2	60.00	120.00
REAR FLOOR PANEL INSULATOR MAT <i>Ne</i>	1	300.00	300.00
REAR TAILLAMP CLIPS L/R - SET <i>Ne</i>	2	30.00	60.00
REAR WINDSCREEN SEAL <i>Ne</i>	1	100.00	100.00
REAR WINDSCREEN SEALANT <i>Ne</i>	1	80.00	80.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

DANNY SOH YEE LENG
2 ARDMORE PARK #15-04
SINGAPORE 259947

Contact : 93632650, 82227080

ESTIMATE

Repair Code : CLM15039

Date in : 30/09/2020

Vehicle Num. : SLT751T

Model : MITSUBISHI ATTRAGE 1.2 CVT

Chassis/Eng# : MMBSTA13AJH000497/3A92UGK5658

Subtotal before discount	2,975.00
Percentage discount 0%	0.00
Sub-total 2	2,975.00
Parts-total	12,041.33

LABOUR

To Transfer Rear Bootlid Mechanism Lock Outer Handle Reflector

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall windscreen (REAR)

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel, rear bumper, rear doors (L/R), and roof top panel.

To remove and reinstall exhaust pipe.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	5,070.00
Parts & Labour Total	17,111.33

*** This is a computer-generated document which requires no signature.***

page 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
01/10/20 L/s.

12 Days.

total: 12083.30

L/s: 9.6K ✓