

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

29-Sep-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1137 S

1 pc	Rear o/s door	\$	791.00	bt
1 pc	o/s rocker panel garnish	\$	286.00	ky
1 pc	Rear o/s wheel cover	\$	116.00	ant
1 pc	Rear bumper o/s side bracket	\$	29.00	x un
1 pc	Rear bumper	\$	696.00	ky
		\$	1,918.00	907
		\$	191.80	
		\$	1,726.20	816.30
		<div>Loss 10%</div> <div>LKK Auto Consultants hence notify the Repairer of the following:<ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</div> <div>Acknowledged by Repairer Signature: Date:</div>		
S/NETT				
1 set	o/s rocker panel garnish clips	\$	38.00	x un
1 set	o/s door stickers	\$	100.00	re
1 pc	Rear o/s fender sticker	\$	60.00	un
1 pc	Rear bumper clips	\$	48.00	x un
	Sundry	\$	50.00	20 180
	To check for rear & rear o/s wheel alignment	\$	80.00	✓
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	x un.
	To refit inner components of the rear o/s doors onto new shell doors	\$	150.00	60
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld & cut rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the front o/s door pillar, etc.	\$	800.00	500
	To putty and spray painting on rear o/s door, o/s rocker panel garnish, rear o/s fender, rear bumper	\$	800.00	600
	To apply rustproofing on the repaired and replaced panels.	\$	180.00	30
		\$	7,449.00	1270.

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Tanpin 97495744

WP 30/9/20 0445pm

1/5 Resurvey after repair

04 days

Handbook

816.30

180

1270

2266.30

1/5 1800

* 4 days