

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

29-Sep-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1137 S

1 pc	Rear o/s door	\$	791.00 <i>bt</i>
1 pc	o/s rocker panel garnish	\$	286.00 <i>Ry</i>
1 pc	Rear o/s wheel cover	\$	116.00 <i>cut</i> ✓
1 pc	Rear bumper o/s side bracket	\$	29.00 <i>x</i>
1 pc	Rear bumper	\$	696.00 <i>Ry</i>
		\$	1,918.00
		\$	191.80
		\$	1,726.20
		Less 10%	
		\$	1,726.20
<div><p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p><ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company<p>Acknowledged by Repairer Signature: _____ Date: _____</p></div>			
S/NETT			
1 set	o/s rocker panel garnish clips	\$	38.00 <i>x</i>
1 set	o/s door stickers	\$	100.00 <i>re</i> ✓
1 pc	Rear o/s fender sticker	\$	60.00 <i>re</i> ✓
1 pc	Rear bumper clips	\$	48.00 <i>x</i>
	Sundry	\$	50.00 <i>20</i>
	To check for rear & rear o/s wheel alignment	\$	80.00 ✓
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 <i>x</i>
	To refit inner components of the rear o/s doors onto new shell doors	\$	150.00 <i>60</i>
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld & cut rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the front o/s door pillar, etc.	\$	800.00 <i>500</i>
	To putty and spray painting on rear o/s door, o/s rocker panel garnish, rear o/s fender, rear bumper	\$	800.00 <i>600</i>
	To apply rustproofing on the repaired and replaced panels.	\$	180.00 <i>30</i>
		\$	7,449.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Tanpin 97495744
WP
2/5 Resurvey after repair
30/9/20 0445pm.
Tanpin P/Heart own.
04 days
Plan head.