



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

30/09/2020

TP Ergo.

Vecon

Accident date: 30/09/2020

Estimated repair cost for vehicle no: SKU2688L SUBARU FORESTER 2.0XT CVT AWD 1

CHASSIS: JF1SJGK85FG053362

S/n	Qty	Items	U/price	Amount
1	1	Front L/H Door <i>Repis</i>		\$920.80 <i>x</i>
2	1	Front L/H Door Lower Garnish <i>ut</i>		\$183.50 <i>✓</i>
3	8	Front L/H Door Lower Garnish Clip <i>new</i>	\$6.50	\$52.00 <i>30</i>
4	1	Rear L/H Door <i>Dented</i>		\$850.40 <i>✓</i>
5	1	Rear L/H Door Lower Garnish <i>ut</i>		\$168.50 <i>✓</i>
6	10	Rear L/H Door Lower Garnish Clip <i>new</i>	\$6.50	\$65.00 <i>30</i>
7	1	Rear L/H Door Inner Insulation <i>new</i>		\$550.00 <i>300(SN)</i>
8	2	Rear L/H Door Hinge <i>2xhol</i>	\$41.00	\$82.00 <i>x</i>
9	1	Rear L/H Door Lock <i>new</i>		\$290.50 <i>x</i>
10	1	Rear L/H Door Weatherstrip <i>new</i>		\$220.50 <i>x</i>
11	1	Rear L/H Door Arch Protector <i>Rubber, ut</i>		\$229.00 <i>135</i>
12	1	Rear L/H Door Inner Trimboard <i>cracked</i>		\$490.50 <i>✓</i>
13	1	Rear L/H Door Framesticker <i>new</i>		\$120.80 <i>30(SN)</i>
14	1	Rear L/H Door Window Motor & Regulator Assy <i>Damaged</i>		\$580.50 <i>235</i>
15	1	Rear L/H Fender <i>Repis</i>		\$960.00 <i>x</i>
16	1	Rear L/H Fender Cowling <i>Dented</i>		\$167.30 <i>x</i>
17	8	Rear L/H Fender Cowling Clip <i>new</i>	\$6.50	\$52.00 <i>30</i>
18	1	Rear L/H Fender Inner Trim Board <i>2xhol</i>		\$408.10 <i>x</i>
19	8	Rear Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$52.00 <i>x</i>
20	1	Rear R/H Lower Arm <i>Best</i>		\$493.20 <i>✓</i>
21	1	Rear R/H Knuckle Arm <i>Damaged</i>		\$264.90 <i>✓</i>
22	1	Rear R/H Knuckle Arm Bearing <i>new</i>		\$261.00 <i>✓</i>
23	1	Rear R/H Trailing Arm <i>Best</i>		\$235.50 <i>✓</i>
24	1	Rear R/H Control Arm <i>Best</i>		\$215.90 <i>✓</i>
25	1set	Rear R/H Shock Absorber (Coilover) <i>Best</i>		\$2,000.00 <i>800(SN)</i>
26	1	Rear R/H Tyre <i>ut</i>		\$550.00 <i>250(SN)</i>
27	1set	Rear R/H Rim <i>ut</i>		\$1,800.00 <i>680(SN)</i>

382070

SN 2080

305656

Subtotal :- \$12,043.60

Labour charges

Remove & refit rear cushion	\$200.00 80
To remove & refit rear R/H fender glass	\$100.00 x
Gum	\$50.00 x
To remove & refit rear R/H undercarriage	\$380.00 220
To check wheel alignment	\$150.00 80
To check wiring	\$100.00 30
Tuff kote	\$150.00 50
Panel beating	\$1,200.00 500
Spray painting	\$1,200.00 500
Subtotal :-	<u>\$3,530.00</u>

15,823.90 Total:- \$15,573.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 6486.56
1/5: 52K
05 Days
52K