

# ESTIMATE

T & C AUTOMOTIVE

Contact: 9007 5148, Chai

Blk 1 Kaki Bukie Avenue 6, Autobay #01-49, Singapore 417883

Date: 01/10/2020

TP ALG.  
Xiao Chen.

Vehicle No.: SBX136S

Make/Model: Toyota Lexus GS300 Auto 3.0

Chassis: JTHBH96S205062547

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Descriptions	Quantity	Unit Price	Total Amount
<b>Spare Parts</b>			
Front bumper <i>deformed.</i>	1	\$1,061.25	\$1,061.25 ✓
Front bumper RH retainer	1	\$75.40	\$75.40 +
Front bumper LH retainer	1	\$75.40	\$75.40 +
Front bumper reinforcement	1	\$591.60	\$591.60 +
Headlamp HID RH set <i>cut</i>	1	\$2,054.75	\$2,054.75 ✓
Headlamp HID LH set	1	\$2,054.75	\$2,054.75 +
Headlamp RH bracket	1	\$171.40	\$171.40 +
Headlamp LH bracket	1	\$171.40	\$171.40 +
Headlamp RH ballast	1	\$781.40	\$781.40 +
Headlamp RH chrome <i>cut</i>	1	\$371.85	\$371.85 ✓
Headlamp LH chrome <i>not new</i>	1	\$371.85	\$371.85 +
Headlamp RH washer chrome (cover)	1	\$512.35	\$512.35 +
Headlamp RH spray nozzle	1	\$61.10	\$61.10 +
Headlamp spray nozzle RH bracket	1	\$781.45	\$781.45 +
Front RH fender <i>not new</i>	1	\$581.90	\$581.90 ✓
Front grille base <i>cut</i>	1	\$561.60	\$561.60 ✓
Front grille chrome <i>not new</i>	1	\$171.45	\$171.45 ✓
Front grille "Lexus" logo	1	\$85.20	\$85.20 ✓
Fog lamp rh <i>cut</i>	1	\$121.10	\$121.10 +
Bonnet rubber <i>not new</i>	1		
			<b>\$10,657.20</b>
		Less 10%	<b>\$1,065.72</b>
			<b>\$9,591.48</b>

## Special Nett

Front bumper clip <i>new</i>	10	\$6.00	\$60.00 <i>30</i>
Front fender inner shield clip <i>new</i>	8	\$6.00	\$48.00 +
Front number plate <i>cracked</i>	1	\$40.00	\$40.00 <i>30</i>
Front number plate casing <i>cut</i>	1	\$180.00	\$180.00 <i>30</i>
Front RH sports rim <i>not new</i>	1	\$550.00	\$550.00 +
		<b>Sub-Total 3</b>	<b>\$878.00</b>

## Labour

Rewiring refocus headlamp.			\$100.00 <i>30</i>
Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$700.00 <i>200</i>
Putty and spray painting all affected parts & areas.			\$800.00 <i>250</i>
Anti-rust undercoat.			\$50.00 +

**Total Labour** \$1,650.00  
**Total Repair Cost** \$12,119.48

total: 4969.20  
2/s: 3.9k  
2/s: 01/10/20  
03 Days.