

N-51 AUTOMOTIVE PTE LTD

Ki Bukit AutoHub
Ki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

EDWARD TAN MENG HONG
BLK 833 HOUGANG CENTRAL #04-604
SINGAPORE 530833

TP China
Xiao Chen

Contact : 97429845

ESTIMATE

Repair Code : CLM16468

Date in : 30/09/2020

Vehicle Num. : SJT8846A

Model : NISSAN X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR

Chassis/Eng# : JN1JANT32Z00001770/MR20859855B

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>replaced</i>	1	594.10	✓ 594.10
FRONT BUMPER LOWER GRILLE <i>could</i>	1	223.70	✓ 223.70
FRONT BUMPER OUTER CHROME MOULDING <i>at</i>	4420.80	171.30	✓ 171.30
FRONT BUMPER SIDE RETAINER L/R <i>per</i>	2	23.40	✓ 46.80
FRONT BUMPER SPONGE <i>could</i>	3978.72	326.50	291.60 326.50
FRONT GRILLE <i>could</i>	1	452.40	✓ 452.40
FRONT GRILLE 'LOGO' EMBLEM <i>per</i>	1	64.90	✓ 64.90
FRONT HEADLAMP L/R <i>L/R could</i>	2	2576.00	2576 5152.00
Subtotal before discount			7,031.70
Percentage discount 10%			703.17
Sub-total 1			6,328.53
FRONT BUMPER CLIPS - SET <i>per</i>	1	50.00	30 50.00
FRONT BUMPER NUMBER PLATE <i>Best</i>	1	25.00	✓ 25.00
FRONT BUMPER NUMBER PLATE HOLDER <i>could</i>	1	50.00	30 50.00
FRONT GRILLE CLIPS - SET <i>per</i>	1	30.00	✓ 30.00
FRONT HEADLAMP LOWER BRACKET L/R <i>could</i>	2	20.00	20 40.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

EDWARD TAN MENG HONG
BLK 833 HOUGANG CENTRAL #04-604
SINGAPORE 530833

Contact : 97429845

ESTIMATE

Repair Code : CLM16468
Date in : 30/09/2020
Vehicle Num. : SJT8846A
Model : NISSAN X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Chassis/Eng# : JN1JANT32Z00001770/MR20859855B

Subtotal before discount	195.00
Percentage discount 0%	0.00
Sub-total 2	195.00
Parts-total	6,523.53

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

Labour Total	1,280.00
Parts & Labour Total	7,803.53

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Cj
4/s 01/10/20
03 days.
total: 4693.72
4/s: 3750