



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

30/09/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP MS16

Denise

Accident date: 29/09/2020

Estimated repair cost for vehicle no: YN9120H MITSUBISHI CANTER FEB21

CHASSIS: FEB21EA10354

3.0 M '15

S/n	Qty	Items	U/price	Amount
1	1	Rear Tailgate <i>Rejis</i>		\$2,550.00 <i>x</i>
2	1	Rear Tailgate Mitsubishi Sticker <i>2</i>		\$85.00 <i>x</i>
3	1	Rear Tailgate 60Km/h Sticker <i>2</i>		\$20.00 <i>x</i>
4	1	Rear Tailgate 18 Pax Sticker		\$20.00 <i>x</i>
5	1	Rear Tailgate Lower Member <i>Rejis</i>		\$1,500.00 <i>x</i>
6	4	Rear Tailgate Hinge <i>all m</i>	\$181.20	\$724.80 <i>x</i>
7	2	Rear Tailgate Side Rubber Stopper <i>all m</i>	\$31.20	\$62.40 <i>x</i>
8	2	Rear Tailgate Side Lock <i>all m</i>	\$209.10	\$418.20 <i>x</i>
9	1	Rear Reinforcement <i>Best</i>		\$1,500.00 <i>900(SN)</i>
10	1	Rear Reinforcement Sticker <i>over</i>		\$150.00 <i>100(SN)</i>
11	2	Rear Tail Lamp <i>LH cut</i>	\$368.20	\$736.40 <i>286</i>
12	2	Rear Tail Lamp Panel <i>LH Best</i>	\$374.40	\$748.80 <i>123</i>
13	1	Rear Number Plate <i>Best</i>		\$50.00 <i>30(SN)</i>
14	1	Rear Number Plate Lamp <i>cauled</i>		\$80.00 <i>55</i>

464 SN 1030
3A8

Subtotal :- \$8,645.60

Labour charges

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$200.00~~ 60

Panel beating

~~\$1,000.00~~ 400

Spray painting

990

\$1,400.00 500.

Subtotal :- \$2,700.00

Total:- \$11,345.60

total : 2268

L/s: 1.9K.

03 Days.

1.9K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: