

AUBURN AUTO PTE LTD
UEN : 200805305G
176 Sin Ming Drive Autocare #04-18, Singapore 575721
Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Vehicle Number : SJZ9146Z (DOA : 26/09/2020)
Make & Model : Volkswagen Polo

Quantity	Description	Repairer's Estimate	
	FRONT		
1	Front Number Plate	\$50.00 CUT	30 ✓
1	Front bumper Tow Cover	\$159.83 MIS	48.95 ✓
1	Right Headlight Clip	\$158.00 ✕ NN	
1	Front number plate base garnish	\$222.12 ✕ NN	
1	Fog light Cover (RH)	\$255.42 ✓ MIS	
1	Front Bumper UnderTray Cover	\$388.86 ✕ NN	
1	Front Grill Right (Grille assy)	\$250.51 ✓ BR	
1	Front Grill Left	\$250.51 ✕ NN	
1	Front Driving Sensor	\$480.00 ✕ NN	
1	Left Chassis Garnish	\$545.00 ✕ NN	
1	Right Chassis Garnish	\$545.00 ✕ NN	
1	Left Side Headlight	\$500.00 ✕ NN	
1	Right Side Headlight	\$500.00 ✓ BR	
1	Front Side Retainer	\$500.00 BR	180 ✓
1	Front Bumper Retainer	\$499.99 ✕ NN	
1	Front Driver Side Panel	\$800.87 ✕ NN	
1	Front Support	\$1,200.00 BR	512 ✓
1	Aircon condenser	\$1,387.00 ✕ NN	
1	Front Reinforcement Bar	\$1,323.00 DD	697 ✓
1	Front Bumper	\$2,499.00 BR	846 ✓
1	BONNET	\$800.00 ✓ DD	
1	Wiper Motor	\$358.23 ✕ NN	
1	Aircon Switch	\$398.22 ✕ NN	
1	Aircon Pipe	\$252.67 ✕ NN	
1	Radiator	\$500.98 ✕ NN	
1	Aircon Compressor	\$500.12 ✕ NN	
1	Front Reinforcement Bar	\$1,500.00 ✕ NN	
1	Wiper Tank	\$217.00 ✓ CRU	
1	FAULTY WIRING	\$1,267.00 ✕ NN	
1	BUMPER BRACKET	\$1,200.00 ✕ NN	
1	Front RIGHT ABSORBER	\$1,249.00 BT	338 ✓
1	Front LEFT ABSORBER	\$1,249.00 BT	338 ✓
1	Front RIGHT BOOT MUDGUARD (Fender)	\$1,200.00 BR	481 ✓
1	Front LEFT BOOT MUDGUARD (Fender)	\$1,200.00 BR	481 ✓
1	Undercarriage (Front lower arm RH & LH)	\$1,500.00 DD	540 ✓
	SIDE		
1	Bumper Clip Right	\$150.00 ✕ NN	
1	Bumper Clip Left	\$150.00 ✕ NN	
1	Bumper Strip	\$200.00 ✕ NN	
1	Front Right Rim	\$200.00 ✓ BR	
1	Front right tyre	\$150.00 CRU	120 ✓
1	Rear Left Door Speaker	\$250.00 ✕ NN	
1	Right Side Fender	\$250.00 ✕ NN	
1	Left Side Mirror	\$350.00 ✕ NN	
1	Right Mirror	\$350.00 ✕ NN	
1	Under Tray Cover	\$350.00 ✕ NN	
1	Right Headlight	\$400.00 ✕ NN	
1	Condenser	\$450.00 ✕ NN	
1	Radiator	\$450.00 ✕ NN	
1	Reinforcement Bar Sponge	\$450.00 ✕ NN	
1	Front Left Door Replace	\$2,000.00 ✕ Repair	
1	Rear Left Door Replace	\$5,000.00 ✕ NN	
1	RIGHT SIDE MIRROR	\$1,200.00 ✕ NN	
1	LEFT SIDE MIRROR	\$1,200.00 ✕ NN	
1	Left Side Fender	\$800.00 ✕ NN	
1	Front Right Door Replace	\$2,000.00 DD	1586 ✓
1	Rear Right Door Replace	\$5,000.00 ✕ NN	8420.88 -10% 7578.79
	LABOUR & MISC		
1	Tow	\$50.00 ✓	
1	Checking of wiring, lighting and resetting	\$850.00 100	
1	Remove and refit rear undercarriage	\$500.00 200	
1	Wheel alignment	\$300.00 60	
1	Remove and replace damaged parts	\$1,000.00 ✕	
1	Apply undercoating on repaired and replaced panel	\$800.00 30	
1	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,200.00 1000	
1	Respray including polishing and waxing on the changed body parts, repaired portortions where consistent to the accident	\$1,000.00 ✓	2440
	Total Repair Cost :	\$52,957.33	

LKK Auto Consultants hence notify the Repairer of the following:
• To reserve defective time parking
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is done a "Without Prejudice" basis
• No illegal modifications is allowed
• Supplementary items must be insured and is subject to final approval from insurance company
Acknowledged by Repairer
Signature: _____
Date: _____

Steve (LKK)
Without Prejudice
01/10/20
Lumpsum
Resurvey After Spray
10 repair days