

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SLH3715S [YOUR INSURED] & SMA20471 [YOUR CLIENT] resurveyed and
ON 19/09/2020. is subject to final approval from Insurance Company

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Acknowledged by Repairer

Signature:

Date:

ESTIMATED REPAIR COSTS FOR SMA20471

QTY	PARTS	AMOUNT
1PC	BOOTLID <i>St Dent</i>	1650.65 \$ 2430.00 ✓
1PC	BOOTLID INNER TRIM <i>HH</i>	\$ 453.44 X
1PC	BOOTLID LOCK <i>HH</i>	\$ 497.85 X
1PC	BOOTLID SWITCH <i>HH</i>	\$ 375.64 X
1PC	BOOTLID LAMP LH <i>mondy crack</i>	\$ 563.49 ✓
1PC	BOOTLID 'BMW' LOGO <i>Hec</i>	75.90 \$ 124.34 ✓
1PC	BOOTLID '520I' EMBLEM <i>Hec</i>	62.55 \$ 98.39 ✓
2PCS	TAIL LAMP LH / RH @ \$1,309.00 <i>2vc</i>	\$ 2,618.00 X
2PCS	TAIL LAMP PANEL LH / RH @ \$396.88 EACH <i>HH</i>	\$ 793.76 X
2PCS	TAIL LAMP LOWER BRACKET LH / RH @ \$198.75 EACH <i>HH</i>	\$ 397.50 X
2PCS	REAR FENDER LH / RH @ \$3,296.57 EACH <i>HH</i>	\$ 6,593.14 X
2PCS	REAR FENDER INNER TRIM LH / RH @ \$399.67 EACH <i>HH</i>	\$ 799.34 X
1PC	REAR BUMPER <i>distorted</i>	1571.95 \$ 2435.00 ✓
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$175.68 EACH <i>HH</i>	13 broken \$ 351.36 ✓
1PC	REAR BUMPER REFLECTOR LH <i>distorted</i>	0/5 HL \$ 193.00 ✓
1PC	REAR BUMPER CARRIER <i>broken</i>	\$ 299.89 ✓
4PC	REAR BUMPER SENSOR @ \$389.00 EACH <i>Dent</i>	220/- SH \$ 1,556.00 ✓
4PC	REAR BUMPER SENSOR HOLDER @ \$67.00 EACH <i>HH</i>	\$ 268.00 X
4PC	REAR BUMPER SENSOR RUBBER O-RING @ \$39.00 EACH <i>HH</i>	\$ 156.00 X
1PC	REAR BUMPER SENSOR WIREHARNESS <i>HH</i>	\$ 574.29 X
1PC	REAR BUMPER SPONGE <i>HH</i>	\$ 319.00 X
1PC	REAR REINFORCEMENT BAR <i>Dent</i>	691.75 \$ 785.30 ✓
2PCS	REAR REINFORCEMENT BAR HOLDER LH / RH @ \$415.67 EACH <i>HH</i>	\$ 831.34 X
1PC	REAR END PANEL <i>HH</i>	\$ 1,364.80 X
1PC	REAR END PANEL TOP GARNISH <i>HH</i>	\$ 413.55 X
1PC	SPARE WHEEL PANEL <i>HH</i>	\$ 1,003.46 X
2PC	SPARE WHEEL QUARTER PANEL LH / RH @ \$413.98 EACH <i>HH</i>	\$ 827.96 X
1PC	SPARE WHEEL PANEL TOP BOARD <i>HH</i>	\$ 1,239.80 X
1PC	REAR EXHAUST PIPE <i>HH</i>	\$ 1,896.58 X
1PC	REAR EXHAUST MOUNTING <i>HH</i>	\$ 207.89 X

1PC	REAR EXHAUST HEAT SHIELD HH	\$ 319.73	X
2PCS	REAR EXHAUST CHROME TIP @ \$566.90 EACH HH	\$ 1,133.80	X

5284.86
107. 4756.37

PARTS SUM: \$ 31,921.64
PARTS LESS 0%: \$ -
PARTS TOTAL: \$ 31,921.64

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR END PANEL SEALANT HH	\$ 80.00	X
*	TO SUPPLY REAR FENDER SEALANT HH	\$ 80.00	X
*	TO SUPPLY REAR WINDSCREEN SEALANT HH	\$ 80.00	X
*	TO SUPPLY REAR FENDER QUARTER GLASS SEALANT HH	\$ 80.00	X
*	TO SUPPLY REAR BUMPER CLIPS H/c	\$ 50.00	30/-
*	TO SUPPLY REAR END PANEL TOP GARNISH CLIPS HH	\$ 50.00	X
*	TO SUPPLY REAR FENDER INNER TRIM CLIPS HH	\$ 50.00	X
*	TO SUPPLY SPARE WHEEL PANEL SEALANT HH	\$ 50.00	X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00	HH
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 1,600.00	500/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 1,400.00	500/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00	40/-
*	TO RNR REVERSE CAMERA	\$ 100.00	HH
*	TO RNR REAR FENDER QUARTER GLASS TO ASSIST WORK LOAD	\$ 250.00	HH
*	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD	\$ 250.00	HH
*	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	\$ 200.00	60/-
*	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$ 250.00	HH
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	30/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00	HH
*	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	\$ 120.00	40/-

LABOUR & S/N TOTAL: \$ 5,790.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 37,711.64

01/10/2020 1730hrs

NA Andrew

L/Sum

J. Ryan

3 days. Check part prices.

6176.37

L/S 4900/-