

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : EMILDA BINTE SULAIMAN
471A UPPER SERANGOON CRESCENT
#08-382
SINGAPORE 531471
TEL: 93369195
ATTN:

Claim No: MC1901446
No: MF1901336
Date: 17 Nov 2020
Policy No: MT/00845858
Veh Reg No: SLC5470K
Make/Model: MAZDA 3 4-DOOR
SEDAN 1.5L
Chassis No: JM6BM42A8G0339213
TP Ins Co: 1ST CAP

Your Ref No: SLC5470K
Claim Type: Third Party
Accident Date: 28/09/2020
TP Veh Reg No: SHC2548M

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SLC5470K

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 REAR BUMPER	1 PC	996.70	
2 REAR BUMPER TOW COVER LH	1 PC	16.50	
3 REAR BUMPER SIDE RETAINER LH	1 PC	38.00	
4 REAR BUMPER CLIPS	12 PC	36.00	
5 REAR BUMPER REINFORCEMENT	1 PC	564.20	
		1,651.40	
	Less 20%	330.28	1,321.12
LABOUR			
6 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	10.00	
7 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
8 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR END PANEL,RR FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	200.00	
9 TO SPRAY REAR BUMPER,REAR FENDER LH,END PANEL.	1 PC	220.00	
		480.00	480.00
		Total	S\$ 1,801.12
		Add GST @ 7%	126.08
		Total Amount Payable	S\$ 1,927.20

TOTAL: SINGAPORE DOLLAR ONE THOUSAND NINE HUNDRED TWENTY SEVEN AND CENTS TWENTY ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 02/10/2020

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 FAX: 6483 6170
Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

0:15/10

SURVEYOR COPY

M/S : EMILDA BINTE SULAIMAN
 471A UPPER SERANGOON CRESCENT
 #08-382
 SINGAPORE 531471
 TEL: 93369195
 ATTN:

Estimate No: MC1901446
 Date: 30 Sep 2020
 Policy No: MT/00845858
 Veh Reg No: SLC5470K
 Make/Model: MAZDA 3 4-DOOR
 SEDAN 1.5L

Your Ref No: SLC5470K
 Claim Type: Third Party
 Accident Date: 28/09/2020
 TP Veh Reg No: SHC2548M

Not Authorized
Recovery By paint
2 days

Estimate Repair Cost to Vehicle No :SLC5470K

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 REAR BUMPER	1 PC	996.70	
2 REAR BUMPER TOW COVER LH	1 PC	16.50	
3 REAR BUMPER SIDE RETAINER LH	1 PC	38.00	
4 REAR BUMPER CLIPS	12 PC	36.00	
5 REAR BUMPER REINFORCEMENT	1 PC	564.20	
6 REVERSE-SENSOR-INNER-LH-&-RH	2 PC	407.20	X
7 REVERSE-SENSOR-HOLDER	4 PC	72.80	X
8 REAR-BOOT-LOCK	1 PC	160.70	X
9 REAR-FENDER-COWLING-LH	1 PC	153.10	X
10 REAR-FENDER-COWLING-CLIPS	4 PC	12.00	X
11 TAILAMP-LH	1 PC	866.80	X
		3,324.00	
	Less 20%	664.80	2,659.20
LABOUR			
12 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
13 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	
14 TO SPRAY-ANTI-RUST-COATING ON AFFECTED AREAS.	1 PC	60.00	X
15 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR END PANEL,RR FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	
16 TO SPRAY REAR BUMPER,REAR FENDER LH,END PANEL.	1 PC	600.00	
		1,260.00	1,260.00



Meng 14-10-20
Man Photo
14-10-20