

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : EMILDA BINTE SULAIMAN
 471A UPPER SERANGOON CRESCENT
 #08-382
 SINGAPORE 531471
 TEL: 93369195
 ATTN:

Estimate No: MC1901446
 Date: 30 Sep 2020
 Policy No: MT/00845858
 Veh Reg No: SLC5470K
 Make/Model: MAZDA 3 4-DOOR
 SEDAN 1.5L

Your Ref No: SLC5470K
 Claim Type: Third Party
 Accident Date: 28/09/2020
 TP Veh Reg No: SHC2548M

Not Authorized
Resurvey B4 paint
2 days

Estimate Repair Cost to Vehicle No :SLC5470K

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BUMPER	1 PC	996.70	✓
2 REAR BUMPER TOW COVER LH	1 PC	16.50	✓
3 REAR BUMPER SIDE RETAINER LH	1 PC	38.00	?
4 REAR BUMPER CLIPS	12 PC	36.00	✓
5 REAR BUMPER REINFORCEMENT	1 PC	564.20	?
6 REVERSE SENSOR INNER LH & RH	2 PC	407.20	X
7 REVERSE SENSOR HOLDER	4 PC	72.80	X
8 REAR BOOT LOCK	1 PC	160.70	X
9 REAR FENDER COWLING LH	1 PC	153.10	X
10 REAR FENDER COWLING CLIPS	4 PC	12.00	X
11 TAILAMP LH	1 PC	866.80	X
		3,324.00	
	Less 20%	664.80	2,659.20
LABOUR			
12 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	10%
13 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	5%
14 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	X
15 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR END PANEL,RR FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	20%
16 TO SPRAY REAR BUMPER,REAR FENDER LH,END PANEL.	1 PC	600.00	22%
		1,260.00	1,260.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Sign

