

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM20010525/Uba3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	15/04/2021	
	ATTN:CYNTHIA			Code:	ASM	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMN 4841K	Veh. Inspected		SKE 3268T	
	Policy No.	VPX/P2320784	Coverage (\$)		0.00	
	Claim No.	S0M02UIL	Excess (\$)		0.00	
	Assign From		Assign Date		01/10/2020	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA VELLFIRE (A)	c.c		2362	
	Engine No.	HIDDEN	Year of Reg.		2011	
	Chassis No.	ANH208152500	Colour		BLACK	
	Odometer	334844 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/50 R18	MICHELIN		6 mm	
	L/H Front Tyre	235/50 R18	MICHELIN		6 mm	
	R/H Rear Tyre	235/50 R18	MICHELIN		6 mm	
	L/H Rear Tyre	235/50 R18	MICHELIN		6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	30/09/2020	Inspection Dat	е	01/10/2020	
	Survey held at	FASTECH AUTO PTE LTD				
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		5 Worki	ing Days	
				_		