



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLP4074JMake & Model : MAZDA3 4-DOOR SEDAN 1.5LYear of Manufacture : 2017Chassis No. : JM6BN22A8H0146316Ins Company : INDIA VS CHINA TAIPINGEngine No. : P520434045Excess : -Policy No. : -Date of Accident : 24.09.2020Time of Accident : 17:10

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimate

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$ 420.00Plus/Less 20% \$ 84.00Total of Cost / List \$ 336.00(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 336.00Labour (Appendix B) \$ 1,350.00Total Repair Cost \$ 1,686.00 1260.24

The above total will be subjected to 7% G.S.T. -20%: 1000

Contact No
Spark Car Care Service Reception

63837103 - Patrick Tia

PatrickTia@sparkcarcare.com

63837730 - Brenda Ng

BrendaNg@sparkcarcare.com

63837466 - Rohani

RohaniM@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

Ngotw@sparkcarcare.com

63838115 - William Wang

WilliamWangKS@sparkcarcare.com

63837362 - Andrew Goh

AndrewCorneliusGoh@sparkcarcare.comName of Surveyor : Quo Qiang 82880282Company : CKKSurvey conducted on : 01/10/20 at _____**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

before paint photos.
P/p.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLP4074J Case Owner : 0

Make & Model : MAZDA3 4-DOOR SEDAN Year Manufacture : 2017

Chassis No : JM6BN22A8H0146316 Engine No : P520434045

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front bumper retainer LH / <i>re</i>	1		\$ 19.70			
2	Front bumper retainer RH X <i>nn</i>	1		\$ 19.70			
3	Front bumper clips / <i>mc</i>	10		\$ 30.00			
4	LH front fender / <i>buc</i>	1		\$ 350.60			
5	0	1					
6	0	1		400.3			
7	0	1		-20%: 320.24			
8	0	1					
9	0	1					
10	0	1					
11	0	1					
12	0	1					
13	0	1					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.