

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 83488489

TP111
Jasper

ESTIMATE

Repair Code : CLM16469

Date in : 30/09/2020

Vehicle Num. : SLR5071A

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31233521/LEB5933536

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Debond</i>	1	762.70	✓ 762.70
REAR BUMPER REFLECTOR L/R <i>2H cancelled</i>	2	141.10	<i>141.10</i> ✓ 282.20
REAR BUMPER SIDE COVER L/R <i>2H Debond</i>	2	195.00	<i>195</i> ✓ 390.00
REAR BUMPER SIDE RETAINER L/R <i>in 2H</i>	2	23.00	<i>23</i> ✓ 46.00
REAR BUMPER UNDER COVER <i>Debond</i>	1	250.00	✓ 250.00
REAR END PANEL <i>Dented</i>	1	415.60	✓ 415.60
REAR END PANEL ANTENNA SENSOR <i>2 cancelled</i>	1	60.10	✓ 60.10
REAR END PANEL BUZZLE SENSOR	1	85.20	✓ 85.20
REAR END PANEL INNER TOP GARNISH <i>Debond</i>	1	98.00	✓ 98.00
REAR EXHAUST CHROME TAIL PIPE <i>Set</i>	1	135.00	✓ 135.00
REAR EXHAUST GASKET <i>new</i>	1	48.30	+ 48.30
REAR EXHAUST HEAT COVER <i>cancelled</i>	1	55.00	✓ 55.00
REAR EXHAUST RUBBER MOUNTING <i>new</i>	2	16.50	+ 33.00
REAR EXHAUST SILENCER BOX <i>new</i>	1	517.70	+ 517.70
REAR FENDER INNER TRIM BOARD L/R <i>2H cancelled</i>	2	295.00	<i>295</i> ✓ 590.00
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH <i>cancelled</i>	1	485.30	<i>327</i> ✓ 485.30
REAR FLOOR PANEL TOP BOARD COVER <i>Debond</i>	1	430.30	<i>306</i> ✓ 430.30
REAR HYBRID INVERTER AIR DUCT <i>cancelled</i>	1	138.70	✓ 138.70

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 83488489

ESTIMATE

Repair Code : CLM16469

Date in : 30/09/2020

Vehicle Num. : SLR5071A

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31233521/LEB5933536

REAR RH FENDER ARCH GARNISH <i>cluded</i>	1	195.00	✓	195.00
REAR RH TAILLAMP <i>cluded</i>	1	474.60	✓	474.60
REAR RH TAILLAMP INNER BLACK GASKET <i>me</i>	1	38.50	✓	38.50
REAR TAILGATE <i>Dented</i>	1	953.30	✓	953.30
REAR TAILGATE 'HYBRID' EMBLEM <i>me</i>	1	75.80	✓	75.80
REAR TAILGATE 'VEZEL' EMBLEM <i>me</i>	1	56.20	✓	56.20
REAR TAILGATE HINGES L/R <i>me</i>	2	50.00	+	100.00
REAR TAILGATE INNER PULL HANDLE <i>me</i>	1	27.50	+	27.50
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>me</i>	2	18.50	+	37.00
REAR TAILGATE INNER TRIM BOARD <i>cluded</i>	1	153.40	✓	153.40
REAR TAILGATE LOCK STRIKER <i>me</i>	1	27.50	+	27.50
REAR TAILGATE MECHANISM LOCK <i>Dented</i>	1	180.00	✓	180.00
REAR TAILGATE RH REFLECTOR <i>cluded</i>	1	413.20	✓	413.20
REAR TAILGATE RH REFLECTOR INNER BLACK GASKET <i>me</i>	1	38.50	✓	38.50
REAR TAILGATE WEATHER STRIP <i>cut</i>	1	96.80	✓	96.80
REAR TAILGATE WINDSCREEN MOULDING L/R <i>me</i>	2	50.00	✓	100.00
REAR TAILGATE WINDSCREEN SEAL T/L <i>me</i>	2	50.00	✓	100.00

*** This is a computer-generated document which requires no signature.***

6162.70
4930.16

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 83488489

ESTIMATE

Repair Code : CLM16469
Date in : 30/09/2020
Vehicle Num. : SLR5071A
Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD
Chassis/Eng# : RU31233521/LEB5933536

		Subtotal before discount	7,890.40
Percentage discount	20%		1,578.08
		Sub-total 1	6,312.32
REAR BUMPER CLIPS - SET	New	1	80.00 80.00 30
REAR BUMPER REVERSE SENSOR - SET	Byd	1	300.00 300.00 200
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	New	2	50.00 100.00 30
REAR HYBRID INVERTER REMOVE & REINSTALL REPROGRAM SYSTEM		1	1500.00 1500.00 500
REAR RH FENDER ARCH GARNISH CLIPS - SET	New	1	30.00 30.00 20
REAR RH TAILLAMP CLIPS - SET	New	1	25.00 25.00 10
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	New	1	50.00 50.00 ✓
REAR TAILGATE NUMBER PLATE	New	1	25.00 25.00 +
REAR TAILGATE NUMBER PLATE HOLDER	New	1	50.00 50.00 +
REAR TAILGATE OUTER GARNISH CLIPS - SET	New	1	40.00 40.00 +
REAR TAILGATE WINDSCREEN SEALANT	New	1	80.00 80.00 60
		Subtotal before discount	2,280.00
Percentage discount	0%		0.00
		Sub-total 2	2,280.00
		Parts-total	8,592.32

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 83488489

ESTIMATE

Repair Code : CLM16469

Date in : 30/09/2020

Vehicle Num. : SLR5071A

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31233521/LEB5933536

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	✓ 80.00
To remove, reinstall tailgate windscreen	120 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60 140.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800 1,100.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	x 100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1000 1,500.00
To apply anti-rust chemical on repaired and replaced panel.	60 120.00
To remove, reinstall tailgate mechanism and check for function	✓ 80.00

2200
Labour Total

3,270.00

Parts & Labour Total

11,862.32

*** This is a computer-generated document which requires no signature.***

page 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin Lj
H/S 01/10/20
08 Days.

total: 8030.16

L/S: G.H.K ✓