

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 01/10/20

3P INSURANCE: AIGMODEL: HYUNDAI IONIQSURVEYOR: LKKVEH NO.: SHD4728SMVA: LOKE WY

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Front Bumper / <i>BR</i>	1		\$418.30
	Front Bumper Bracket Top RH ? / <i>BR</i>	1		\$35.00
	Front Bumper Bracket RH ? <i>X</i>	1		\$28.00
	Front Bumper Side Bracket Support RH / <i>BR</i>	1		\$12.00
	Front Bumper Centre Moulding / <i>BR</i>	1		\$188.00
	Front Bumper Grille <i>X</i>	1		\$186.90
	Frt Bumper Reinforcement ? <i>X</i>	1		\$1,075.10
	Frt Bumper Towing Cover <i>X</i>	1		\$29.00
	Frt Bumper Lip <i>X</i>	1		35.10
	Frt Bumper License Plate / <i>BR</i>	1		\$17.40
	Frt Bumper Clips / <i>MC</i>	10		\$22.00
	Radiator Grille / <i>BR</i>	1		\$1,409.10
	Radiator Grille Up <i>X</i>	1		\$48.30
	Bonnet <i>X</i>	1		\$2,253.80
	Flap Assy Active Air Upper RH <i>X</i>	1		\$356.00
	Front Bumper Plate Garnish <i>X</i>	1		\$188.00
	Day Light RH <i>X</i>	1		\$642.50
	Headlamp RH / <i>BR</i>	1		\$1,993.65
	Headlamp Support Panel Assy <i>BR</i>	1		\$949.30
	Front Fender RH / <i>BR</i>	1		\$490.70
	Rear Bumper <i>X</i> / <i>BR</i>	1		\$459.40
	Rear Bumper Cover Clips / <i>MC</i>	10		\$22.00
	Rear Bumper Towing Cover <i>X</i>	1		\$98.80
	Rear Bumper Reflector Lamp LH RH <i>X</i>	1		\$63.80
	Rear Bumper Centre Moulding Assy / <i>CHT</i>	1		\$451.25
	Rear Bumper Lower Centre Moulding Assy <i>X</i>	1		\$155.00
	Rear Fog Lamp <i>X</i>	1		\$201.50
SPARE PARTS SUB TOTAL				\$11,794.80
LESS 20%				\$2,358.96
DISCOUNTED SPARE PARTS TOTAL				\$9,435.84
	Frt Number Plate with Trim Cover / <i>CR4</i>	1		\$55.00 Nett
	Rear Bumper Rubber Mat / <i>MC</i>	1		\$50.00 Nett
	Rear Number Plate with Trim / <i>CHT</i>	1		\$55.00 Nett
	Reverse Sensor / <i>Shah</i>	1		\$180.00 Nett
	Emblem Ioniq <i>X</i>	1		\$31.30 Nett
	Emblem- Blue Drive <i>X</i>	1		\$26.60 Nett
DISCOUNTED SPARE PARTS & NETT TOTAL				\$9,833.74

ART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Panel Beating		\$700 00	500 640
	Spray Painting		\$1,000 00	600
	Remove / Replace Reverse Sensor		\$120 00	30
	Remove/ Install Radiator & Aircon Condenser		\$150 00	X
	Tuff Kote		\$90 00	30
	Check Lighting		\$60 00	30
	LABOUR TOTAL			\$2,120.00
	ESTIMATE TOTAL			\$11,953.74
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Steve (LKK) 1/10/20, 2.00pm
 8322 8813 LKL P/L
 Steve chen @ lkk auto-com 4 days
 P/P
 Ry Bef spy

Date/Time: 01.10.2020 11:16

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO.: 305425621

COMER

AS COMFORT TRANSPORTATION PTE LTD

COMER NO. 7010045

RESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(P)

(O)

COUNT CARD NO.

REGN NO. SHD4728S

MILEAGE

MAKE: HYUNDAI

FUEL

E 1/2 F

MODEL IONIQ(G3)

DATE/TIME IN 30.09.2020 20:00

YR OF MANUF 16.01.2020

TARGET DATE

CHASSIS CODE KMHCB51CVLU189998

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 30.09.2020

NATURE: 3P 30.09.2020

S/NO

LABOR CODE

DESCRIPTION



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHD4728S

YY

Vehicle No.:

SHD4728S

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard