



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0717/2020/NS
DATE : 30-Sep-20
WIP : 51427

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : NICOLAE SASARAN
ADDRESS : 40 KEPPEL BAY DRIVE
#04-97
SINGAPORE 098655
TELEPHONE : HP +65 81891617
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070054141
VEHICLE NO : **SMS 9563 D**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 23/3/2020
ENGINE NO : CHZ C34759
CHASSIS NO : WAUZZZ8V1LA004278
MILEAGE : 5909KM
DATE IN : 30-Sep-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Sep-20
PLACE OF ACCIDENT : PAYA LEBAR ROAD AND UBI AVE 3 JUNCTION

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 9563 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250
3	TO DISMANTLE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,500.00	1000
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES, RHS FRONT DOOR AND RHS FRONT FENDER.	\$ 3,000.00	1650
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,672.00	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 9563 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Rebuilt</i>	\$	1,987.00	✓ 1589.60
2 FRONT BUMPER FIXING PARTS <i>new</i>	\$	185.00	+
3 FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$	38.00	+
4 FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$	159.00	+
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	530.00	+
6 FRONT BUMPER CLOSING ELEMENT - RH <i>new</i>	\$	293.00	+
7 FRONT BUMPER COVER TRIM - RH <i>cut</i>	\$	161.00	✓ 128.40
8 WHEEL HOUSING LINER ADAPTER - RH <i>new</i>	\$	37.00	+
9 RADIATOR GRILLE <i>cut</i>	\$	1,406.00	✓ 1124.80
10 RADIATOR GRILLE CLOSING ELEMENT <i>new</i>	\$	189.00	+ ✓ 150.80
11 FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	\$	186.00	+
12 FRONT REINFORCEMENT BEAM <i>new</i>	\$	715.00	? X
13 FRONT BUMPER FOAM FILLER PIECE <i>Rebuilt</i>	\$	187.00	? ✓ 149.60
14 FOAM FILLER PIECE COVER <i>new</i>	\$	121.00	? X
15 AIRCON STICKER <i>new</i>	NEC \$	8.00	✓ 5.68
16 CAUTION SIGN STICKER <i>new</i>	NEC \$	14.00	✓ 10.80
17 SIGNAL HORN - RH LOW TONE <i>new</i>	\$	197.00	+
18 FRONT FENDER - RH <i>Rebuilt</i>	\$	841.00	✓ 672.80
19 FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$	71.00	? X
20 FRONT FENDER BRACKET - RH <i>new</i>	\$	38.00	+
SUB TOTAL SPARE PARTS	:	\$	7,363.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 9563 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 FRONT FENDER BRACKET - RH <i>new</i>		\$ 27.00	X
22 FRONT FENDER BRACE <i>Best.</i>		\$ 95.00	✓ 75.68
23 WHEEL HOUSING LINER - RH <i>new</i>		\$ 167.00	X
24 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>		\$ 88.00	X
25 BONNET <i>Repair</i>		\$ 3,134.00	X
26 BONNET ATTACHMENT PARTS		\$ 163.00	X
27 BONNET LID HINGE - LH / RH	2	\$ 122.00	X
28 BONNET CATCH HOOK		\$ 89.00	X
29 BONNET STRIKER - RH		\$ 109.00	X
30 BONNET EDGE PROTECTION		\$ 28.00	X
31 BONNET LID LOCK		\$ 212.00	X
32 LED HEADLIGHT - RH <i>Cracked.</i>		\$ 5,455.00	✓ 4364.00
33 LIFT CYLINDER - RH <i>new</i>		\$ 141.00	X
34 RADIATOR AIR GUIDE - RH <i>new</i>		\$ 24.00	X
35 RADIATOR AIR GUIDE - UPPER CENTRE <i>new</i>		\$ 12.00	X
36 FRONT NO PLATE <i>new</i>	S/N	\$ 60.00	✓ 60.00
37 SUNDRIES <i>new</i>		\$ 200.00	✓ 12.80
TOTAL SPARE PARTS	:	\$ 17,489.00	
TOTAL LABOUR CHARGES	:	\$ 6,672.00	
GRAND TOTAL	:	\$ 24,161.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King.*
SURVEYED DATE : *01/10/2020*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not Authorised, 05 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT