



# Jin Auto Services Pte Ltd

LKK Jasper

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

8/1/2020

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR GBH3401R ( TOYOTA DYNA )

1	1 PC	FRONT BUMPER	D.S	683.90	\$	685.90
2	1 PC	FRONT BUMPER RH BRACKET	Ben	271.20	\$	271.30
3	1 PC	FRONT GRILLE	one		\$	501.20
4	1 PC	FRONT GRILLE SEAL	one		\$	27.40
5	2 PCS	RH FRONT HEADLAMP	o/s one 1pc	925.10	\$	1,950.20
					\$	3,436.00
		less 25%			\$	(859.00)
					\$	2,577.00
6	1 PC	NUMBER PLATE	3mt		\$	40.00
7		SPRAY PAINTING			\$	780.00
8		LABOUR CHARGE			\$	580.00
9		WIRING CHECK			\$	35.00
					\$	4,012.00

not Authorized

2 days  
P/P \$ 2879.10

8/10/20  
Whelp be. After sign.

P- 2458.50  
25%  
P- 1844.10  
L- 1035.00  
2879.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before the spray painting
- To display damaged part(s) during the survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer