

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Sep 2020 Sendback Est	29 Sep 2020 13:28 \$21,432.93	01 Oct 2020 15:42 Edit Adj Rpt	\$21,432.93 Edit Estimates	\$21,432.93 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS				
Insured: SITI ANISAH BINTE AHMAD , ID: S8851710E				
Vehicle Reg. No.: SLC1396T		Date of Loss: 24/09/2020 05:00 - :59 [52 Months and 21 Days From LTA Reg Date (Man Yr)]		
Claim Type: OD / SNM20D203549/C01/THAMYL		Policy/Cover Note No.: DMPCSNW00044142000 (Comprehensive)		
		Excess: S\$500.00		
Repairer: Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126				
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Pauline Tham]				
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 12/10/2020]				
Driver/Custodian: MAHENDRAN PANNEERSELVAN (/ Male) , NRIC: S9303789H Email:				
Adj Asg. Remarks: Please survey/advise whether economical to repair vehicle.				
ASSOCIATED MAIL RECEIVED View All Compose Case Mail				
There are no mail for this case.				
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete				
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Claim Documents

SLC1396T (SNM20D203549/C01/THAMYL)

OD

Sep 24 2020 5:00AM

[SITI ANISAH BINTE AHMAD]

Jin Auto Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	29/09/20 13:28	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/10/20 10:06	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page ▼ ☒

No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	29/09/20 13:13	Other		Load JPG	☒
2	29/09/20 13:13	Other		Load JPG	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/10/20 17:57	Chassis Number		Load JPG	☒
2	05/10/20 18:00	General View		Load JPG	☒
3	05/10/20 18:00	General View		Load JPG	☒
4	05/10/20 18:00	General View		Load JPG	☒
5	05/10/20 18:00	General View		Load JPG	☒
6	05/10/20 18:00	General View		Load JPG	☒
7	05/10/20 18:00	General View		Load JPG	☒
8	05/10/20 18:00	General View		Load JPG	☒
9	05/10/20 18:00	General View		Load JPG	☒
10	05/10/20 18:00	General View		Load JPG	☒
11	05/10/20 18:00	General View		Load JPG	☒
12	05/10/20 18:00	General View		Load JPG	☒
13	05/10/20 18:00	General View		Load JPG	☒
14	05/10/20 18:00	General View		Load JPG	☒
15	05/10/20 18:00	General View		Load JPG	☒
16	05/10/20 18:00	General View		Load JPG	☒
17	05/10/20 18:00	General View		Load JPG	☒
18	05/10/20 18:00	General View		Load JPG	☒
19	05/10/20 18:00	General View		Load JPG	☒
20	05/10/20 18:01	General View		Load JPG	☒
21	05/10/20 18:01	General View		Load JPG	☒
22	05/10/20 18:01	General View		Load JPG	☒
23	05/10/20 18:01	General View		Load JPG	☒
24	05/10/20 18:01	General View		Load JPG	☒
25	05/10/20 18:01	General View		Load JPG	☒
26	05/10/20 18:01	General View		Load JPG	☒
27	05/10/20 18:01	General View		Load JPG	☒
28	05/10/20 18:01	General View		Load JPG	☒
29	05/10/20 18:01	General View		Load JPG	☒
30	05/10/20 18:01	General View		Load JPG	☒
31	05/10/20 18:01	General View		Load JPG	☒
32	05/10/20 18:01	General View		Load JPG	☒
33	05/10/20 18:01	General View		Load JPG	☒
34	05/10/20 18:01	General View		Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
35	05/10/20 18:01	General View		Load JPG	☒
36	05/10/20 18:01	General View		Load JPG	☒
37	05/10/20 18:01	General View		Load JPG	☒
38	05/10/20 18:01	General View		Load JPG	☒
39	05/10/20 18:01	General View		Load JPG	☒
40	05/10/20 18:01	General View		Load JPG	☒
41	05/10/20 18:01	General View		Load JPG	☒
42	05/10/20 18:01	General View		Load JPG	☒
43	05/10/20 18:01	General View		Load JPG	☒
44	05/10/20 18:01	General View		Load JPG	☒
45	05/10/20 18:01	General View		Load JPG	☒
46	05/10/20 18:01	General View		Load JPG	☒
47	05/10/20 18:01	General View		Load JPG	☒
48	05/10/20 18:01	General View		Load JPG	☒
49	05/10/20 18:01	General View		Load JPG	☒
50	05/10/20 18:01	General View		Load JPG	☒
51	05/10/20 18:01	General View		Load JPG	☒
52	05/10/20 18:01	General View		Load JPG	☒
53	05/10/20 18:01	General View		Load JPG	☒
54	05/10/20 18:01	General View		Load JPG	☒
55	05/10/20 18:01	General View		Load JPG	☒
56	05/10/20 18:01	General View		Load JPG	☒
57	05/10/20 18:01	General View		Load JPG	☒
58	05/10/20 18:01	General View		Load JPG	☒
59	05/10/20 18:01	General View		Load JPG	☒
60	05/10/20 18:01	General View		Load JPG	☒
61	05/10/20 18:01	General View		Load JPG	☒
62	05/10/20 18:01	General View		Load JPG	☒
63	05/10/20 18:02	General View		Load JPG	☒
64	05/10/20 18:02	General View		Load JPG	☒
65	05/10/20 18:02	General View		Load JPG	☒
66	05/10/20 18:02	General View		Load JPG	☒
67	05/10/20 18:02	General View		Load JPG	☒
68	05/10/20 18:02	General View		Load JPG	☒
69	05/10/20 18:02	General View		Load JPG	☒
70	05/10/20 18:02	General View		Load JPG	☒
71	05/10/20 18:02	General View		Load JPG	☒
72	05/10/20 18:02	General View		Load JPG	☒
73	05/10/20 18:02	General View		Load JPG	☒
74	05/10/20 18:02	General View		Load JPG	☒
75	05/10/20 18:02	General View		Load JPG	☒
76	05/10/20 18:02	General View		Load JPG	☒
77	05/10/20 18:02	General View		Load JPG	☒
78	05/10/20 18:02	General View		Load JPG	☒
79	05/10/20 18:02	General View		Load JPG	☒
80	05/10/20 18:02	General View		Load JPG	☒
81	05/10/20 18:02	General View		Load JPG	☒
82	05/10/20 18:02	General View		Load JPG	☒
83	05/10/20 18:02	General View		Load JPG	☒
84	05/10/20 18:02	General View		Load JPG	☒
85	05/10/20 18:02	General View		Load JPG	☒
86	05/10/20 18:02	General View		Load JPG	☒
87	05/10/20 18:02	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail Print
88	05/10/20 18:02	General View		Load JPG ☒
89	05/10/20 18:02	General View		Load JPG ☒
90	05/10/20 18:02	General View		Load JPG ☒
91	05/10/20 18:02	General View		Load JPG ☒
92	05/10/20 18:02	General View		Load JPG ☒
93	05/10/20 18:02	General View		Load JPG ☒
94	05/10/20 18:02	General View		Load JPG ☒
95	05/10/20 18:02	General View		Load JPG ☒
96	05/10/20 18:02	General View		Load JPG ☒
97	05/10/20 18:02	General View		Load JPG ☒
98	05/10/20 18:02	General View		Load JPG ☒
99	05/10/20 18:02	General View		Load JPG ☒
100	05/10/20 18:02	General View		Load JPG ☒
101	05/10/20 18:02	General View		Load JPG ☒
102	05/10/20 18:02	General View		Load JPG ☒
103	05/10/20 18:02	General View		Load JPG ☒
104	05/10/20 18:02	General View		Load JPG ☒
105	05/10/20 18:02	General View		Load JPG ☒
106	05/10/20 18:02	General View		Load JPG ☒
107	05/10/20 18:02	General View		Load JPG ☒
108	05/10/20 18:02	General View		Load JPG ☒
109	05/10/20 18:02	General View		Load JPG ☒
110	05/10/20 18:02	General View		Load JPG ☒
111	05/10/20 18:02	General View		Load JPG ☒
112	05/10/20 18:02	General View		Load JPG ☒
113	05/10/20 18:02	General View		Load JPG ☒
114	05/10/20 18:02	General View		Load JPG ☒
115	05/10/20 18:02	General View		Load JPG ☒
116	05/10/20 18:02	General View		Load JPG ☒

Documentation			1 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail Print
1	29/09/20 13:10	E-filed GIA report		Load PDF
2	29/09/20 13:10	AUDATEX		Load PDF

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	29/09/20 16:59	Used 2016 Honda Mobilio 1.5A RS i-VTEC Luxe for Sale _ Autocar Pte Ltd - sgCarMart		Load PDF
2	29/09/20 16:59	SLC1396T Margin \$19,900 & PARF_COE Rebate Enquiry		Load PDF
3	30/09/20 09:59	Marked Audatex Estimate for repairer		Load PDF

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	09/10/20 12:06	LETTER		Load PDF
2	09/10/20 12:06	LTA REBATE		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

Remarks from China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

29.9.20 Surveyed. 30.9.20 Noted Jouis Authorised Repair. 1.10.20 Jouis feedback that there is Supplementary Engine Block assy. So assign out to external surveyor as vehicle is not economical to repair.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20010556/UQF3S2**Date:** 09/10/2020**REFERENCE**

Insured/Claimant: SITI ANISAH BINTE AHMAD Policy No: DMPCSNW00044142000

Date of Loss: 24/09/2020

Nature of Claim: OD

Claim No: SNM20D203549/C01/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC1396T	Engine No:	L15Z12871826
Make & Model:	HONDA MOBILIO, 1.5 RS Basic (A)	Chassis No:	MRHDD4870GP000139
Reg. Date:	03/05/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Orange		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,655.00	17,655.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,777.93	3,777.93	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,432.93	21,432.93	0.00	0.00
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	21,432.93	20,932.93	500.00	2.33
+ GST 7.00/7.00% (S\$)	1,500.31	1,465.31	35.00	2.33
Nett Amount (S\$)	22,933.24	22,398.24	535.00	2.33

INSPECTION

Date of Assignment:	01/10/2020	Present Location:	Jin Auto Services Pte Ltd (Defu)
Date Inspected:	02/10/2020	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	0.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$60,000.00
OMV :	\$19,047.00
PARF Rebate (1) :	\$14,285.00
Quota Premium Paid :	\$43,843.00
COE Rebate (2) :	\$25,688.00
Total Rebate (1) + (2) = :	\$39,973.00

The total amount incurred will be Market Value \$60,000.00 minus Total Rebate \$39,973.00 = \$20,027.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Oct 2020)
Parts:	M1-MPV	HONDA MOBILIO 1.5 RS Basic (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC1396T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		17,655.00 F	*17,655.00 F
						F=Franchise part.
Total Parts (S\$)					17,655.00	17,655.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOTAL LABOUR	New	3,777.93	3,777.93
Gross Labour Cost (\$\$)			3,777.93	3,777.93

Report was unsubmitted during this print-out.

< END OF ESTIMATES >