

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 1 Oct 2020

ASSESSMENT FOR REPAIR: YAMAHA CZD300A / XMAX300 - FBM9517A

Chassis No.:
 Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard	\$140.00 / CRK
1 pc	Front mudguard right	\$110.00 / CRK
1 pc	• Right front fork	\$780.00 / SCR
1 pc	Left front fork	\$780.00 X SVL
1 pc	Front wheel shaft	\$95.00 X SVL
1 pc	• Front brake disk	\$275.00 ? X SVL
1 pc	• Steering stem	\$255.00 ? / DEF.
2 pcs	• Steering stem bearings @ \$45.00	\$90.00 ? / NBL
1 pc	Headlamp assy	\$395.00 / SET CRK
1 pc	Black front upper cover	\$315.00 / CRK SCR
1 pc	Black front lower cover	\$245.00 / CRK
1 pc	Right fairing	\$325.00 / SCR
1 pc	Right view mirror	\$140.00 X SVL
1 pc	Yamaha emblem	\$50.00 / NBL
1 pc	Lower right cover	\$185.00 / SCR
1 pc	• Right footstep	\$295.00 / SCR
1 pc	• Exhaust connector	\$75.00 ? / NBL
1 pc	• Exhaust assembly	\$750.00 ? X R.
		<hr/>
		\$5,300.00
	Less discount 10%	\$530.00
		<hr/>
		\$4,770.00
	<u>Special nett items</u>	
1 pc	Front tyre	\$145.00 X SVL
1 pc	Front sport rim	\$550.00 X SVL
1)	• Towing charges	\$100.00 X
2)	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$700.00 450
3)	To replace and balance front wheel rim	\$150.00 X NN
4)	To knock, straighten chassis & body balancing	\$380.00 X NN
5)	Spray painting	\$350.00 200
6)	Reset meter	\$120.00 X NN
	Repair Exhaust	\$100

7)

- To replace and refit and align front forks

\$180.00 ?/90.

Total Estimate

\$7,265.00

Note: The above estimate is subjected to the prevailing GST of 7%

NA2 LKK

2/10/20 1330

L/S

3 DAYS

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS



For Bike Production Pte Ltd