

# ASSIGNMENT

File No: \_\_\_\_\_ Date: \_\_\_\_\_

Insured Cos: \_\_\_\_\_

INSURANCE TYPE: RES / RES / EVA / INV / MV

INSURED VEHICLE NO: \_\_\_\_\_

Model/Options: \_\_\_\_\_

Colour: \_\_\_\_\_

Sp. Reading: \_\_\_\_\_

Engine No: \_\_\_\_\_

Cat No: \_\_\_\_\_

Gen. Cond. Good (Fair / Poor / Burnt)

Steering: (In order) / Jammed / Locked / Burnt or

Brake: (In order) / Jammed / Leaked / Burnt or

Wash: Nil / S/Rim / (STD) W/Rim or

Tyre Size: F: \_\_\_\_\_ R: \_\_\_\_\_

BSI / DUT / EX / NOVA / GY / PS / LIZA / VIC / OITS / PIR / SUMIT / TOYO / YOKO or (DUNLAP), (BS (R))

Front RUBal: \_\_\_\_\_ mm RUBal: \_\_\_\_\_ mm

UBal: \_\_\_\_\_ mm UBal: \_\_\_\_\_ mm

DDA: \_\_\_\_\_

Survey held at: RICE PRODUCTION

Das. of Damages: (Frt) / (Rear) / (DIS) / HIS / UIC / Rocktop or

The UIC / Chassis frame / Body structure affected due to damage: \_\_\_\_\_

Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: FBM 9517A Yr Regn: 26 MAY 2018

Type: M. Car / (M. Cycle) / BUS / Van / Lorry / Taxi / Private Motor / Truck / Tractor or

Make: YAMAHA XMAX 300 cc 292

Colour: GREY NO: Insured / Sid / Nil (N/A)

Sp. Reading: 23,712 TIRadp: Insured / Sid / Nil (N/A)

Engine No: \_\_\_\_\_

Cat No: MH3540846JK003811

Gen. Cond. Good (Fair / Poor / Burnt)

Steering: (In order) / Jammed / Locked / Burnt or

Brake: (In order) / Jammed / Leaked / Burnt or

Wash: Nil / S/Rim / (STD) W/Rim or

Tyre Size: F: 120 / 70 R15 R: 140 / 70 R14

BSI / DUT / EX / NOVA / GY / PS / LIZA / VIC / OITS / PIR / SUMIT / TOYO / YOKO or (DUNLAP), (BS (R))

Front RUBal: 3 mm RUBal: 4 mm

UBal: \_\_\_\_\_ mm UBal: \_\_\_\_\_ mm

DDA: \_\_\_\_\_

Survey held at: RICE PRODUCTION

Das. of Damages: (Frt) / (Rear) / (DIS) / HIS / UIC / Rocktop or

The UIC / Chassis frame / Body structure affected due to damage: \_\_\_\_\_

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

COE Rebate \$5,439.00

Repair Limit \$9K. informed repairs. waiting for repair.

Repair cost based on marked estimate (excluding checked items) \$2,550.00

L/S \$3700.00 (RED: \$4433.00, 54%)

Days Of Repair: 3

Resurvey No. of Trip: 2 Survey Fee: \_\_\_\_\_

22/10/20 TYPIST

Lump Sum: 1.9.1.13 L/S \$3700.00

Add Fee:  Site Insp (\$ \_\_\_\_\_)  Interview (\$ \_\_\_\_\_)  Tech. Invo (\$ \_\_\_\_\_)  Weekend (\$ \_\_\_\_\_)

ALG LLS