

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 05 Oct 2020

## **Preliminary Advice**

Vehicle No	: FBM9517A	Accident Date	: 30/09/2020
Make	: YAMAHA XMAX 300	Policy No.	: 1800062519
Assignment Date	: 05/10/2020	Excess	: S\$0.00
Date of Inspection	: 02/10/2020	Est. Duration of Repair	: 3
Inspection At	: BIKE PRODUCTION PTE LTD (HQ) 610 SERANGOON ROAD SINGAPORE 218216		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,265.00
Revised Amount	:S\$	3,206.00
Check Items (Estimated)	:S\$	1,480.50
Total	:S\$	4,686.50

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	15,000.00
COE / PARF Rebate	:S\$	5,439.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,561.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :