

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE.

速 良 摩 哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒杆噴漆
代理保險：車禍
賠償及買賣汽車

EVAR AIR-CONDITIONING & ENGINEERING PTE LTD DATE: 01/10/2020

DOA : 29/09/2020

ESTIMATE REPAIR FOR VEHICLE NO. SKN 4886 E (MAZDA 6)

	Description	List Price
1 pc	Rear bumper	\$ 1,290.00
2 pcs	Centre reverse sensor @S\$230.00	\$ 460.00
1 pc	Rear bumper reinforcement	\$ 620.00
10 pcs	Bumper clips @S\$8.00	\$ 80.00
2 pcs	Bumper side retainer @S\$45.00	\$ 90.00
2 pcs	Towing cover @S\$40.00	\$ 80.00
1 pc	Rear end panel	\$ 700.10
		\$ 3,320.10
	Less : 20%	\$ (664.02)
		\$ 2,656.08
	<u>Special Nett Items</u>	
	To spray anti-rust	\$ 100.00
	Labour charges for knocking & replacing parts.	\$ 600.00
	Spraypainting	\$ 700.00
	TOTAL :	\$ 4,056.08