

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE.

速 良 摩 哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒杆噴漆
代理保險：車禍
賠償及買賣汽車

EVAR AIR-CONDITIONING & ENGINEERING PTE LTD DATE: 01/10/2020

DOA : 29/09/2020

ESTIMATE REPAIR FOR VEHICLE NO. SKN 4886 E (MAZDA 6)

	Description	List Price
1 pc	Rear bumper <i>DD/pe 1206.20</i>	\$ 1,290.00 ✓
2 pcs	Centre reverse sensor @SS\$230.00 <i>slu hhd 203.60 x 2 =</i>	\$ 460.00 ✓ 407.20
1 pc	Rear bumper reinforcement <i>DD 528.30</i>	\$ 620.00 2
10 pcs <i>1 set</i>	Bumper clips @SS\$8.00 <i>neu 50.00</i>	\$ 80.00 ✓
2 pcs	Bumper side retainer @SS\$45.00 <i>n 7</i>	\$ 90.00 X
2 pcs	Towing cover @SS\$40.00 <i>re 24.90 x 2 = 49.80</i>	\$ 80.00 ✓
1 pc	Rear end panel <i>n</i>	\$ 700.10 X
		\$ 3,320.10
	Less : 20%	\$ (664.02)
		\$ 2,656.08
	<u>Special Nett Items</u>	
	To spray anti-rust <i>n 1</i>	\$ 100.00 X
	Labour charges for knocking & replacing parts.	\$ 600.00 400
	Spraypainting	\$ 700.00 500
	TOTAL :	\$ 4,056.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*not about
or
1/5 \$2150
3 days
take the whole up
5/10/20*

*p. 2257.50
102
1801.20
2701.20
2160.*