

## AUTO BULLOX PTE LTD

53 Ubi Avenue 1#01-25 Paya Ubi Industrial Park Singapore 408934

Tel: 6844 4290 Fax: 6841 6043 Kaman Koh: 9769 9299 Email: motoricarzgarage@gmail.com

UEN:201919765N

### 3RD PARTY CLAIM ESTIMATION

Vehicle number : SKD2226B  
 Make / Model : BMW/523i  
 Chassis number : WBAFP32040C88676  
 Accident date : 30/9/2020  
 Reference :

TP ALG.  
Khanchara.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Unit Price SGD \$

| Qty                                   | Particulars                                  | Unit Price SGD \$      |
|---------------------------------------|--|------------------------|
| <u>PARTS REPLACEMENT - LIST ITEMS</u> |  |                        |
| 1                                     | REAR BUMPER REINFORCEMENT <i>Best.</i>       | 630.00 ✓               |
| 1                                     | REAR BUMPER REINFORCEMENT BEAM <i>crackd</i> | 165.00 ✓               |
| 1                                     | REAR BUMPER INNER BRACKET <i>crackd.</i>     | 183.00 ✓               |
| 2                                     | REAR BUMPER BRACKET <i>LH Dand.</i>          | 175.00 ✓ <i>87.50.</i> |
| 1                                     | REAR BUMPER CENTRE UPPER HOLDER <i>new</i>   | 60.00 x                |
| 1                                     | REAR BUMPER CENTRE LOWER HOLDER <i>new</i>   | 90.00 x.               |
| 1                                     | REAR BUMPER UNDER COVER <i>tom</i>           | 135.00 ✓               |
| 1                                     | REAR BUMPER TOW COVER <i>Missing</i>         | 67.00 ✓                |
| 1                                     | REAR BUMPER SIDE COVER LH <i>Distortd</i>    | 63.00 ✓                |
| 1                                     | REAR BUMPER SIDE COVER RH <i>New</i>         | 63.00 x.               |
| 4                                     | PDC SENSOR <i>2 pieces dand</i>              | 1480.00 ✓ <i>500.</i>  |
| 4                                     | SENSOR HOLDER <i>new</i>                     | 80.00 ✓                |
| 1                                     | REAR LH BUMPER HEAT INSULATOR <i>new</i>     | 55.00 x                |
| 1                                     | BOOTLID <i>Distorted</i>                     | 1750.00 ✓              |
| 1                                     | REAR BOOTLID HINGE LH <i>Best</i>            | 125.00 ✓               |
| 1                                     | REAR BOOTLID HINGE RH <i>New</i>             | 125.00 x               |
| 1                                     | BOOTLID PUSH BUTTON <i>New</i>               | 121.00 x               |
| 1                                     | BOOTLID LOCK <i>Dand</i>                     | 465.00 ✓               |
| 1                                     | BOOTLID LOCK STRIKER <i>New</i>              | 55.00 x.               |
| 1                                     | TRUNK LID POWER LOCK DRIVE <i>New</i>        | 180.00 x               |
| 1                                     | BOOTLID LOCK CABLE <i>new</i>                | 123.00 x               |
| 1                                     | BOOTLID WEATHERSTRIP <i>at</i>               | 214.00 ✓               |
| 1                                     | BOOTLID LOGO <i>new</i>                      | 29.00 ✓                |
| 1                                     | BOOTLID SPOILER <i>crackd</i>                | 215.00 ✓               |
| 1                                     | REAR LOCK SENSOR <i>Dand</i>                 | 65.00 ✓                |
| 1                                     | REAR END PANEL <i>Distorted</i>              | 910.00 ✓               |
| 1                                     | REAR FENDER LH <i>Distorted.</i>             | 1900.00 ✓ <i>1650</i>  |
| 1                                     | REAR TAILLAMP PANEL LH <i>Distorted</i>      | 315.00 ✓               |
| 1                                     | REAR FLOOR PANEL <i>Repair</i>               | 715.00 x.              |
| 1                                     | REAR INNER WHEELHOUSE PANEL <i>Repair</i>    | 1209.00 x.             |
| 1                                     | REAR CHASSIS FRAME LH <i>Repair</i>          | 921.00 x.              |
| 1                                     | REAR MEMBER EXTENSION LH <i>Repair</i>       | 115.00 x               |
| 1                                     | REAR TAILLAMP LH <i>Smashed.</i>             | 630.00 ✓               |
| 1                                     | REAR BOOTLID LAMP LH <i>crackd</i>           | 480.00 ✓               |
| 1                                     | BOOTLID INNER TRIM <i>Delnd</i>              | 135.00 ✓               |
| 1                                     | REAR FENDER INNER TRIM LH <i>crackd</i>      | 198.00 ✓               |
| 1                                     | END PANEL INNER TRIM <i>new</i>              | 155.00 x               |
| 1                                     | SPARE TYRE TOP BOARD                         | 750.00 x.              |

| Qty   | Particulars  | Unit Price - SGD \$ |
|---|--|---------------------|
| <u>PARTS REPLACEMENT - LIST ITEMS</u>         |  |                     |
| 1   | FLOOR COMPARTMENT INNER TRIM <i>HP all</i>         | 110.00 <i>x</i>     |
| 1   | REAR FENDER INNER SHIELD LH <i>tom</i>             | 115.00 <i>✓</i>     |
| 1   | REAR EXHAUST <i>Distorted</i>                      | 1750.00 <i>✓</i>    |
| 2   | REAR EXHAUST MOUNTING <i>tom</i>                   | 60.00 <i>✓</i>      |
| 2   | TAILPIPE TIP CHROME <i>Distorted</i>               | 140.00 <i>✓</i>     |
| 1   | REAR EXHAUST HEAT SHIELD LH <i>Distorted</i>       | 125.00 <i>✓</i>     |
| 1   | REAR EXHAUST HEAT SHIELD RH <i>HP m</i>            | 125.00 <i>x</i>     |
| 1   | FRONT HEADREST LH <i>HP m</i>                      | 819.00 <i>x</i>     |
| 1   | FRONT HEADREST RH <i>HP m</i>                      | 819.00 <i>x</i>     |
| 1   | REAR WINDSCREEN <i>shattered</i>                   | 1430.00 <i>✓</i>    |
| 1   | REAR WINDSCREEN MOULDING <i>m</i>                  | 280.00 <i>✓</i>     |
|   |  | 20919.00            |
|   | Less 10%   | 2091.90             |
|   | Subtotal   | 18827.10            |
|   | Balance C/F  |                     |
| <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u> |  |                     |
| 1   | REAR NUMBER PLATE <i>new</i>                       | 80.00 <i>x</i>      |
| 1 SET   | REAR BUMPER CLIP <i>new</i>                        | 30.00 <i>✓</i>      |
| 1 SET   | REAR FENDER INNER SHIELD CLIP <i>new</i>           | 20.00 <i>✓</i>      |
| 1 SET   | REAR FENDER INNER TRIM CLIP <i>new</i>             | 20.00 <i>✓</i>      |
| 1   | REAR BUMPER ( AFTER MARKET ) <i>Distorted</i>      | 2400.00 <i>1500</i> |
| 1   | JOINT SEALANT <i>new</i>                           | 120.00 <i>60</i>    |
| 1   | WINDSCREEN SEALANT <i>new</i>                      | 120.00 <i>60</i>    |
|   | Subtotal   | 2790.00             |
|   | Balance C/F  | 21617.10            |
| <u>LABOUR AND MISCELLANEOUS CHARGES</u>       |  |                     |
|   | Balance B/F  | 21617.10            |
| 1   | CHECK REAR WIRING AND LIGHTNING SYSTEM             | 80.00 <i>30</i>     |
| 2   | REMOVE, REFIT REAR LINING, TRIM AND GANRISH        | 200.00 <i>100</i>   |
| 3   | REMOVE, RENEW REAR REVERSE SENSOR                  | 100.00 <i>60</i>    |
| 4   | REMOVE, RENEW REAR EXHAUST ASSY                    | 120.00 <i>✓</i>     |
| 5   | DIAGNOIS CHECK AND REAR FAULT CODE                 | 400.00 <i>150</i>   |
| 6   | REMOVE AND RENEW FRONT BOTH HEADREST               | 200.00 <i>x</i>     |
| 7   | REMOVE AND REFIT FUEL TANK                         | 120.00 <i>80</i>    |
| 8   | REMOVE AND REFIT REAR WINDSCREEN                   | 120.00 <i>✓</i>     |
| 9   | TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW | 200.00 <i>80</i>    |
| 10  | COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT       | 150.00 <i>x</i>     |
| 11  | PANEL BEATING ON AFFECTED AREAS                    | 2500.00 <i>1600</i> |
| 12  | SPRAY PAINTING ON AFFECTED AREAS                   | 2000.00 <i>1400</i> |
| 13  | APPLY ANTI RUST ON AFFECTED AREAS                  | 150.00 <i>100</i>   |
|   | Subtotal   | 6340.00             |
|   | Grand total  | 27957.10            |

*Total: 17222.35*  
*C/S: 9.5K*  
*(Nett Value)*  
*Adrian G*  
*02/10/20*  
*10 Pays.*  
*Nett Value: 9.5K*