



FALCON-AIR

UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD #28-01 SPRINGLEAF TOWER
SINGAPORE 079909

Estimate : ES707750

Date : 01/10/2020

Vehicle Num. : XD 8011K

Make/Model : MIT. FV51JJD4RDEA

Chassis/Eng# :

Accident Date : 23/09/2020

Claim No. :

Reference : OD

Policy No. :

Attention : Motor Claim Department

Contact : 62227733 Fax No. : 63273869 /3870

S/N Quantity Particular Unit Price Amount S\$

PARTS PURCHASED :				
1.	1 PC	FRONT WINDSCREEN GLASS	350 ✓	1200
2.	1 PC	FRONT WINDSCREEN RUBBER	25 ✓	300.
3.	1 PC	IU BRACKET	26 ✓	26.00
4.	1 PC	REAR VIEW MIRROR	30 ✓	140.00
5.	3 PC	FRONT WIPER ARM	30 ✓	270.00
6.	3 PC	FRONT WIPER BLADE	35 ✓	105.00
7.	3 PC	WIPER ARM CAP	15 ✓	45.00
8.	1 PC	BONNET	180 ✓	1,850.00
9.	2 PC	BONNET HINGES	180 x 2 = 360	680.00
10.	2 PC	BONNET LOCK	160 ✓	320.00
11.	1 PC	BONNET FUSO EMBLEM	80 ✓	120.00
12.	1 PC	BONNET GRILLE TOP	320 ✓	320.00
13.	10 PC	BONNET GRILLE TOP FEMALE CLIPS	5.00 ✓	50.00 X
14.	10 PC	BONNET GRILLE TOP MALE CLIP	5.00 ✓	50.00 X
15.	1 PC	BONNET GRILLE LOWER	320 ✓	320.00
16.	10 PC	BONNET GRILLE LOWER MALE CLIP	5.00 ✓	50.00 X
17.	10 PC	BONNET GRILLE LOWER FEMALE CLIP	5.00 ✓	50.00 X
18.	1 PC	O/S CORNER PANEL	460 ✓	460.00
19.	4 PC	O/S CORNER PANEL FEMALE CLIP	5.00 ✓	20.00 X
20.	4 PC	O/S CORNER PANEL MALE CLIP	5.00 ✓	20.00 X
21.	3 PC	O/S CORNER PANEL RUBBER SEAL	35 ✓	105.00
22.	1 PC	O/S CORNER PANEL LAMP	540 ✓	540.00

CONTINUE / ...

6030

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD #28-01 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department

Contact : 62227733 Fax No. : 63273869 /3870

Estimate : ES707750

Date : 01/10/2020

Vehicle Num. : XD 8011K

Make/Model : MIT. FV51JJD4RDEA

Chassis/Eng# :

Accident Date : 23/09/2020

Claim No. :

Reference : OD

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	BONNET CABLE <i>3m ✓</i>		280.00 ✓
24.	1 PC	FRONT BUMPER <i>Best ✓</i>		2,150.00 ✓
25.	2 PC	FRONT BUMPER BRACKET <i>11 X</i>		920.00 X
26.	2 PC	FRONT BUMPER LIGHT GARNISH - TOP <i>n/s m.s o/s car ✓</i>	460.00	320.00 ✓
27.	2 PC	FRONT BUMPER LIGHT GARNISH - LOWER <i>n/s m.s o/s car ✓</i>	160.00	320.00 ✓
28.	2 PC	HEADLAMP <i>11 X</i>	970.00	1,940.00 X
29.	2 PC	SIGNAL LAMP <i>11 X</i>	760.00	1,520.00 X
30.	2 PC	BONNET DAMPER - SMALL <i>best ✓</i>	180.00	360.00 ✓
31.	1 PC	BONNET RUBBER SEAL <i>best ✓</i>		98.00 ✓
32.	1 PC	O/S FRONT WINDSCREEN PILLAR - OUTER <i>best ✓</i>	1,400	2,150.00 ✓
33.	1 PC	O/S FRONT WINDSCREEN PILLAR - INNER <i>best ✓</i>	1,200	1,980.00 ✓
34.	1 PC	O/S FRONT WINDSCREEN PILLAR INNER TRIM <i>11 X</i>		350.00 X
35.	10 PC	O/S FRONT WINDSCREEN PILLAR INNER TRIM CLIP <i>11 X</i>	5.00	50.00 X
36.	1 PC	O/S FRONT DOOR <i>3uc ✓</i>		2,650.00 ✓
37.	1 PC	O/S FRONT DOOR HINGE - TOP <i>best ✓</i>	100	180.00 ✓
38.	1 PC	O/S FRONT DOOR HINGE - LOWER <i>best ✓</i>	100	180.00 ✓
39.	1 PC	O/S FRONT DOOR CHECKER <i>best ✓</i>	100	150.00 ✓
40.	1 PC	O/S FRONT DOOR GLASS <i>c/w door ✓</i>		560.00 X
41.	1 PC	O/S FRONT DOOR OUTER MOULDING <i>c/w door ✓</i>		210.00 X
42.	1 PC	O/S FRONT DOOR GLASS CHANNEL <i>c/w door ✓</i>		320.00 X
43.	1 PC	O/S SIDE MIRROR STAY <i>best ✓</i>		780.00 ✓
44.	1 PC	O/S SIDE MIRROR - RECTANGLE <i>best ✓</i>		80.00 ✓
45.	1 PC	O/S FRONT DOOR INNER LOCK <i>c/w door ✓</i>		370.00 X
46.	1 PC	O/S FRONT DOOR GLASS REGULATOR GEAR <i>c/w door ✓</i>		360.00 X

CONTINUE / ...

9288

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-6880 Fax: 6454-7867

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD #28-01 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department

Contact : 62227733 Fax No. : 63273869 /3870

Page 3 / 7
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-I
GST REG. NO.: 19-9501140-I

Estimate : ES707750

Date : 01/10/2020

Vehicle Num. : XD 8011K

Make/Model : MIT. FV51JJD4RDEA

Chassis/Eng# :

Accident Date : 23/09/2020

Claim No. :

Reference : OD

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
47.	1 PC	O/S FRONT DOOR GLASS REGULATOR GEAR MOTOR <i>c/w door</i>		450.00 <i>X</i>
48.	1 PC	O/S FRONT DOOR BOARD <i>5.00</i> <i>c/w door</i>		890.00 <i>X</i>
49.	12 PC	O/S FRONT DOOR BOARD CLIP <i>11 X</i>	5.00	60.00 <i>X</i>
50.	1 PC	O/S FRONT DOOR INNER HANDLE <i>11 X</i>		160.00 <i>X</i>
51.	1 PC	O/S FRONT DOOR WEATHERSTRIP <i>c/w door</i>		280.00 <i>X</i>
52.	1 PC	O/S FRONT DOOR WEATHERSTRIP INNER <i>c/w door</i>		350.00 <i>X</i>
53.	1 PC	O/S FRONT DOOR SMALL GARNISH <i>11 X</i>		90.00 <i>X</i>
54.	1 PC	O/S FRONT DOOR TOP HANDLE <i>11 X</i>		540.00 <i>X</i>
55.	1 PC	N/S FRONT DOOR INNER LOCK <i>11 X</i>		370.00 <i>X</i>
56.	1 PC	N/S FRONT DOOR SMALL GARNISH <i>11 X</i>		90.00 <i>X</i>
57.	1 PC	N/S FRONT DOOR TRIM BOARD <i>11 X</i>		790.00 <i>X</i>
58.	1 PC	N/S FRONT DOOR TRIM BOARD CLIP <i>11 X</i>		5.00 <i>X</i>
59.	1 PC	O/S FRONT WHEEL ARCH PANEL - OUTER <i>Body</i>		1,650.00 <i>X</i>
60.	1 PC	O/S FRONT WHEEL ARCH PANEL - INNER <i>11 X</i>		1,250.00 <i>X</i>
61.	1 PC	O/S FRONT WHEEL ARCH GARNISH - TOP <i>Dis</i>		650.00 <i>X</i>
62.	1 PC	O/S FRONT WHEEL ARCH GARNISH - LOWER <i>Dis</i>		420.00 <i>X</i>
63.	1 PC	<i>Rec</i> O/S B PILLAR - OUTER <i>Body</i>		1,970.00 <i>X</i>
64.	1 PC	O/S 'B' PILLAR - INNER <i>11 X</i>		1,840.00 <i>X</i>
65.	1 PC	O/S 'B' PILLAR TRIM BOARD <i>11 X</i>		860.00 <i>X</i>
66.	10 PC	O/S 'B' PILLAR TRIM BOARD CLIP <i>11 X</i>	5.00	50.00 <i>X</i>
67.	1 PC	O/S 'B' PILLAR INNER HANDLE <i>11 X</i>		450.00 <i>X</i>
68.	1 PC	O/S 'B' PILLAR GLASS WITH MOULDING <i>11 X</i>		760.00 <i>X</i>
69.	1 PC	FRONT WIPER LINKAGE <i>24</i>		460.00 <i>X</i>
70.	1 PC	FRONT WIPER LINKAGE MOTOR <i>Sm</i>		540.00 <i>X</i>

CONTINUE / ...

5690

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD #28-01 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department

Contact : 62227733 Fax No. : 63273869 /3870

CO. REG. NO.: 1995-01140-I
GST REG. NO.: 19-9501140-I

Estimate : ES707750

Date : 01/10/2020
Vehicle Num. : XD 8011K
Make/Model : MIT. FV51JJD4RDEA
Chassis/Eng#:
Accident Date : 23/09/2020
Claim No. :
Reference : OD
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
71.	1 PC	CABIN TORSION BAR ASSY <i>But</i>		1,780.00 <i>1400</i>
72.	2 PC	CABIN MOUNTING - FRONT <i>Tw</i>	680.00	1,360.00 <i>500 x 2 = 1000</i>
73.	2 PC	CABIN MOUNTING - REAR <i>Tw</i>	540.00	1,080.00
74.	1 PC	FRONT PANEL INNER ASSY <i>2 X</i>		1,840.00 <i>X</i>
75.	2 PC	FRONT PANEL BRACKET <i>Tw</i>	95.00	190.00
76.	1 PC	BRAKE FLUID RESERVIOR <i>De</i>		95.00
77.	1 PC	BRAKE FLUID RESERVIOR CAP <i>De</i>		20.00
78.	1 PC	WIPER WASHER TANK <i>De</i>		180.00
79.	1 PC	WIPER WASHER TANK MOTOR <i>De</i>		140.00
80.	1 PC	RADIATOR SPARE TANK <i>De</i>		190.00
81.	1 PC	AIR-CON SUCTION PIPE <i>But</i>		380.00
82.	1 PC	AIR-CON DISCHARGE PIPE <i>But</i>		380.00
83.	1 PC	ENGINE OIL SYSTEM WARNING ASSY <i>one</i>		275.00
84.	1 PC	BRAKE HOSE BRACKET <i>But</i>		140.00
85.	1 PC	BRAKE HOSE CENTRE BRACKET <i>1 X</i>		85.00 <i>X</i>
86.	2 PC	HEATER HOSE - TOP <i>Tw</i>	45.00	90.00
87.	2 PC	HEATER HOSE - LOWER <i>Tw</i>	45.00	90.00 <i>X</i>
88.	2 PC	HEATER HOSE JOINT <i>Tw</i>	50.00	100.00 <i>X</i>
89.	1 PC	STEERING BOX <i>1 X</i>		3,400.00 <i>X</i>
90.	1 PC	TURBO INTERCOOLER <i>But/Pur</i>		3,800.00 <i>3500</i>
91.	1 PC	RADIATOR <i>But/Pur</i>		3,600.00
92.	1 PC	RADIATOR FAN COWLING <i>Eng</i>		360.00
93.	1 PC	RADIATOR FAN BLADE <i>Eng</i>		280.00
94.	1 PC	RADIATOR FAN CLUTCH <i>1 X</i>		760.00 <i>X</i>

CONTINUE / ...

13300

FALCON-AIR AUTO SERVICES PTE LTD

[a subsidiary of Falcon-Air Holdings Pte Ltd]

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S[528840] Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop [Blk I / Blk K] S[128226] Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD #28-01 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department

Contact : 62227733 Fax No. : 63273869 /3870

Estimate : ES707750

Date : 01/10/2020

Vehicle Num. : XD 8011K

Make/Model : MIT. FV51JJD4RDEA

Chassis/Eng# :

Accident Date : 23/09/2020

Claim No. :

Reference : OD

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
95.	1 PC	O/S CORNER PANEL BRACKET <i>N/S</i>		60.00 <i>X</i>
96.	1 PC	DASHBOARD <i>D.S</i>		1,850.00 <i>✓</i>
97.	1 PC	DASHBOARD REINFORCEMENT BAR <i>but</i>		2,400.00 <i>✓</i>
98.	1 PC	SPEEDO METER <i>2re</i>		2,480.00 <i>✓</i>
99.	1 PC	STEERING COLUMN <i>11 X</i>		970.00 <i>X</i>
100.	1 PC	STEERING COLUMN LOWER COVER <i>11 X</i>		260.00 <i>X</i>
101.	1 PC	STEERING WHEEL LOWER COVER <i>11 X</i>		240.00 <i>X</i>
102.	1 PC	O/S DASHBOARD AIR CON VENT <i>11 X</i>		240.00 <i>X</i>
103.	1 PC	O/S DASHBOARD AIR CON VENT GARNISH <i>11 X</i>		480.00 <i>X</i>
104.	1 PC	N/S DASHBOARD AIR CON VENT <i>11 X</i>		240.00 <i>X</i>
105.	1 PC	N/S DASHBOARD AIR CON VENT GARNISH <i>11 X</i>		480.00 <i>X</i>
106.	1 PC	DASHBOARD CENTRE GARNISH <i>11 X</i>		640.00 <i>X</i>
107.	1 PC	CENTRE CONSOLE BOX <i>D.S</i>		2,150.00 <i>✓</i>
108.	1 PC	CENTRE CONSOLE BOX GARNISH <i>D.S</i>		240.00 <i>✓</i>
109.	1 PC	FUSE BOX ASSY <i>11 X</i>		1,180.00 <i>X</i>
110.	1 PC	FUSE BOX COVER <i>11 X</i>		140.00 <i>X</i>
111.	1 PC	N/S DASHBOARD LOWER COVER <i>11 X</i>		350.00 <i>X</i>
112.	1 PC	N/S DASHBOARD SIDE COVER <i>11 X</i>		190.00 <i>X</i>
113.	1 PC	GLOVE BOX ASSY <i>11 X</i>		400.00 <i>X</i>
114.	1 PC	COOLING COIL HOUSING <i>2re</i>		1,800.00 <i>✓</i>
115.	1 PC	HEATER COIL HOUSING ASSY <i>2re</i>		1,850.00 <i>✓</i>
116.	1 PC	AIR-CON BLOWER HOUSING ASSY <i>2re</i>		1,650.00 <i>✓</i>
117.	2 PC	DASHBOARD TOP AIR VENT <i>11 X</i>	245.00	490.00 <i>X</i>
118.	1 PC	AIR-CLEANER AIR DUCT <i>11 X</i>		640.00 <i>X</i>

CONTINUE / ...

12840

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD #28-01 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department

Contact : 62227733 Fax No. : 63273869 /3870

Page 6 / 7
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-I
GST REG. NO.: 19-9501140-I

Estimate : ES707750

Date : 01/10/2020
Vehicle Num. : XD 8011K
Make/Model : MIT. FV51JJD4RDEA
Chassis/Eng# :
Accident Date : 23/09/2020
Claim No. :
Reference : OD
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
119.	2 PC	FRONT CABIN DAMPER	440.00	880.00
120.	1 PC	WIRE HARNESS		2,890.00
121.	1 PC	BRAKE HOSE - THIN		270.00
122.	1 PC	BRAKE HOSE - THICK		320.00
Total Parts Purchased S\$:				87,139.00
10.00% Of The Above Parts S\$:				8,713.90
Based On Cost Plus S\$:				95,852.90
SPECIAL NETT ITEMS :				
1.	1 PC	SEALANT		40.00
2.	1 PC	COOLANT		40.00
3.	2BTLs	BRAKE FLUID	40.00	80.00
Special Nett Total S\$:				160.00
LABOUR :				
		TO REMOVE/REFIX FRONT WINDSCREEN GLASS	120	150.00
		VACCUM AND RE-GAS FOR AIR-CON	100	150.00
		CHECK LIGHT SYSTEM AND WIRING	30	180.00
		TRANSFER DOOR PARTS	30	150.00
		TOWING CHARGES	300	300.00
		TO REMOVE/REPLACE DASHBOARD	300	400.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

9-48028
+102
9-52830.80
L. 5760
58590.8
602
34



FALCON-AIR

UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD #28-01 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department

Contact : 62227733 Fax No. : 63273869 /3870

Estimate : ES707750

Date : 01/10/2020

Vehicle Num. : XD 8011K

Make/Model : MIT. FV51JJD4RDEA

Chassis/Eng# :

Accident Date : 23/09/2020

Claim No. :

Reference : OD

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REMOVE/REPLACE COOLING COIL HOUSING AND ETC	180	400.00
		TO CRANE CABIN TO FACILIATE REPAIRS AND TO FIX BACK	300	1,000.00
		TO STRAIGHTEN CHASSIS FRAME	11 X	800.00
		TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL, REPAIR		
		INNER PANEL, REWELD INNER PANEL, REPLACE ACCIDENT DAMAGED	2800	3,500.00
		PARTS AND ALIGN THE SAME	1500	4,000.00
		TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS		
		TO DROP STEERING BOX TO FACILIATE REPAIRS AND TO FIX	100	400.00
		BACK		
		TO REMOVE BRAKE BOOSTER TO FACILATE REPAIRS AND TO FIX	100	400.00
		BACK		
		TO REMOVE INNER TRIM, SEAT, GARNISH AND ETC TO FACILATE		
		REPAIRS AND TO FIX BACK	150	350.00
		TO REPLACE BRAKE HOSES AND TO BLEED AIR	<	300.00
		TO REPLACE WIRE HARNESS	11 X	500.00
		TO SCAN AND CLEAR FAULT CODES	11 X	250.00
		Labour Total S\$:		13,230.00

5760

E. & O.E.

Total S\$: 109,242.90

=====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg