

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 1-Oct-20

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC 3379 C

INSURANCE: China Taiping

| Description                                           | Qty  | List Price  | Amount       |   |
|-------------------------------------------------------|------|-------------|--------------|---|
| Rear Door (LH) <i>Distru</i>                          | 1    | \$ 1,789.90 | \$ 1,789.90  | ✓ |
| Rear Door Outer Handle (LH) <i>low</i>                | 1    | \$ 124.80   | \$ 124.80    | X |
| Rear Door Trim Board (LH) <i>HH</i>                   | 1    | \$ 613.60   | \$ 613.60    | X |
| Rear Door Protector(LH) <i>HH</i>                     | 1    | \$ 166.20   | \$ 166.20    | X |
| Rocker Panel Outer Garnish <i>low</i>                 | 1    | \$ 715.60   | \$ 715.60    | X |
| Rear Bumper <i>Cut</i>                                | 1    | \$ 459.40   | \$ 459.40    | ✓ |
| Rear Bumper Side retainer (LH) <i>SVC</i>             | 1    | \$ 85.80    | \$ 85.80     | X |
| Rear Bumper Cover Clips <i>Hec</i>                    | 1    | \$ 22.00    | \$ 22.00     | ✓ |
| Rear Bumper Side Under(LH) <i>HH</i>                  | 1    | \$ 123.10   | \$ 123.10    | X |
| Rear tray tools box LH <i>HH</i>                      | 1    | \$ 693.20   | \$ 693.20    | X |
| Rear Fender(LH) <i>Cut</i>                            | 1    | \$ 1,768.30 | \$ 1,768.30  | ✓ |
| Rear Fender Inner Panel (LH) <i>HH</i>                | 1    | \$ 1,406.20 | \$ 1,406.20  | X |
| Rear Fender SHIELD REAR PIECE ( LH ) <i>HH</i>        | 1    | \$ 173.60   | \$ 173.60    | X |
| Rear Fender SHIELD Frt Piece (LH) <i>HH</i>           | 1    | \$ 165.50   | \$ 165.50    | X |
| Rear Fender Air-Duct (LH) <i>HH</i>                   | 1    | \$ 87.30    | \$ 87.30     | X |
| Rear Fender Trim Board (LH) <i>HH</i>                 | 1    | \$ 788.75   | \$ 788.75    | X |
| Fuel Lid Cover LH <i>SVC</i>                          | 1    | \$ 83.30    | \$ 83.30     | X |
| FUEL LID GARNISH COVER <i>HH</i>                      | 1    | \$ 361.20   | \$ 361.20    | X |
| REAR FENDER TRIM BOARD TOP GARNISH (LH) <i>HH</i>     | 1    | \$ 167.90   | \$ 167.90    | X |
| Assy BSD Blind Spot Radar (LH) <i>HH</i>              | 1    | \$ 1,625.00 | \$ 1,625.00  | X |
| Rear Tyre Rim (LH) <i>2 x 15</i>                      | 1    | \$ 1,124.20 | \$ 1,124.20  | ✓ |
| Rear Wheel Hup-Cap (LH) <i>Cut 1 Bt</i>               | 1    | \$ 346.40   | \$ 346.40    | ✓ |
| Rear Wheelbearing & Hub assy <i>2 Distru</i>          | 1    | \$ 554.00   | \$ 554.00    | ✓ |
| Rear Trailing Arm(LH) <i>2 distru</i>                 | 1    | \$ 265.40   | \$ 265.40    | ✓ |
| Rear Assist (LH) <i>2 distru</i>                      | 1    | \$ 227.90   | \$ 227.90    | ✓ |
| Rear shock Absorber(LH) <i>2 distru</i>               | 1    | \$ 230.50   | \$ 230.50    | ✓ |
| Rear Shock Absorber Mounting (LH) <i>HH</i>           | 1    | \$ 133.10   | \$ 133.10    | X |
| Rear Absorber stopper (LH) <i>HH</i>                  | 1    | \$ 137.60   | \$ 137.60    | X |
| Rear Absorber Cover (LH) <i>HH</i>                    | 1    | \$ 175.60   | \$ 175.60    | X |
| Rear Crossmember <i>HH</i>                            | 1    | \$ 1,468.70 | \$ 1,468.70  | X |
| Stabilizer Bar <i>HH</i>                              | 1    | \$ 387.30   | \$ 387.30    | X |
| Stabilizer Link (LH) <i>HH</i>                        | 1    | \$ 147.30   | \$ 147.30    | X |
| Rear Upper Arm(LH) <i>HH 2 distru</i>                 | 1    | \$ 239.50   | \$ 239.50    | ✓ |
| Rear Lower Arm(LH) <i>HH 2 distru</i>                 | 1    | \$ 393.10   | \$ 393.10    | ✓ |
| Rear Knuckle Arm (LH) <i>2 distru</i>                 | 1    | \$ 538.10   | \$ 538.10    | ✓ |
|                                                       |      |             |              |   |
| SUB TOTAL                                             |      |             | \$ 17,789.35 |   |
| LESS 20%                                              |      |             | \$ 3,557.87  |   |
| DISCOUNTED TOTAL                                      |      |             | \$ 14,231.48 |   |
| Rear Door Tel No.Sticker(LH) <i>Hec</i>               | SN 1 | \$ 10.00    | \$ 10.00     | ✓ |
| Rear Door Comfortdelgro & Apps Sticker(LH) <i>Hec</i> | SN 1 | \$ 80.00    | \$ 80.00     | ✓ |

|                                            |  |  |  |  |           |   |            |              |       |
|--------------------------------------------|--|--|--|--|-----------|---|------------|--------------|-------|
| SPARE TYRE PANEL TOP COVER SILICON HH      |  |  |  |  | SN        | 1 | \$ 250.00  | \$ 250.00    | X     |
| Rear Tyre(LH) HH                           |  |  |  |  | SN        | 1 | \$ 216.00  | \$ 216.00    | X     |
|                                            |  |  |  |  |           |   |            |              |       |
|                                            |  |  |  |  |           |   |            |              |       |
|                                            |  |  |  |  | SUB TOTAL |   |            | \$ 556.00    |       |
| <b>Labour Charge</b>                       |  |  |  |  |           |   |            |              |       |
| Panel Beating                              |  |  |  |  |           |   |            |              |       |
| Spray Painting Charge                      |  |  |  |  |           | 1 | \$1,400.00 | \$1,400.00   | 800/- |
| Wiring Charge                              |  |  |  |  |           | 1 | \$1,200.00 | \$1,200.00   | 700/- |
| Tuff Kote                                  |  |  |  |  |           | 1 | \$160.00   | \$160.00     | 30/-  |
| Towing Charge                              |  |  |  |  |           | 1 | \$140.00   | \$140.00     | 40/-  |
| Remove/Refix Undercarriage (RR)            |  |  |  |  |           | 1 | \$80.00    | \$80.00      | HH    |
| Re-set Rear ABS System                     |  |  |  |  |           | 1 | \$400.00   | \$400.00     | 150/- |
| Transfer of Door Mechanism REAR            |  |  |  |  |           | 1 | \$400.00   | \$400.00     | HH    |
| Re-set Rear Power Window System            |  |  |  |  |           | 1 | \$80.00    | \$80.00      | 60/-  |
| Four Wheel Alignment                       |  |  |  |  |           | 1 | \$200.00   | \$200.00     | HH    |
| Remove/Refix Undercarriage (Frt)           |  |  |  |  |           | 1 | \$120.00   | \$120.00     | 60/-  |
| Diagnostic & Resetting To Erase Fault Code |  |  |  |  |           | 1 | \$400.00   | \$400.00     | HH    |
|                                            |  |  |  |  |           | 1 | \$550.00   | \$550.00     | 180/- |
| <b>TOTAL LABOUR</b>                        |  |  |  |  |           |   |            | \$5,130.00   |       |
| <b>ESTIMATE TOTAL</b>                      |  |  |  |  |           |   |            | \$ 19,917.48 |       |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

02/10/2020 e 1700hr

Hot Air Gun  
Part by Part.

6 days

Man

LKK Auto

8

Photo after  
reflex with  
damaged parts.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# BIFROST AUTO PTE LTD

## REPAIR SUPPLEMENTARY

DATE: 6-Oct-20

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC 3379 C (S)

INSURANCE: Chink Te-ping

| Description                                                                                                                                                                                                    | Qty | List Price | Amount    |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------------|-----------|
| Tail Lamp(LH) <i>crashy work</i>                                                                                                                                                                               | 1   | \$ 870.40  | \$ 870.40 |
|                                                                                                                                                                                                                |     |            |           |
| SUB TOTAL                                                                                                                                                                                                      |     |            | \$ 870.40 |
| LESS 20%                                                                                                                                                                                                       |     |            | \$ 174.08 |
| DISCOUNTED TOTAL                                                                                                                                                                                               |     |            | \$ 696.32 |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. |     |            |           |

*yan*

*2kk Auto*

*8*