

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 1-Oct-20

INSURANCE: China太平

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC 3379 C

CC6 / CTI 20010572 / Dra³

Description	Qty	List Price	Amount	
Rear Door (LH) <i>Destru</i>	1	\$ 1,789.90	\$ 1,789.90	✓
Rear Door Outer Handle (LH) <i>low</i>	1	\$ 124.80	\$ 124.80	X
Rear Door Trim Board (LH) <i>HH</i>	1	\$ 613.60	\$ 613.60	X
Rear Door Protector(LH) <i>HH</i>	1	\$ 166.20	\$ 166.20	X
Rocker Panel Outer Garnish <i>low</i>	1	\$ 715.60	\$ 715.60	X
Rear Bumper <i>Cut</i>	1	\$ 459.40	\$ 459.40	✓
Rear Bumper Side retainer (LH) <i>SVC</i>	1	\$ 85.80	\$ 85.80	X
Rear Bumper Cover Clips <i>Hec</i>	1	\$ 22.00	\$ 22.00	✓
Rear Bumper Side Under(LH) <i>HH</i>	1	\$ 123.10	\$ 123.10	X
Rear tray tools box LH <i>HH</i>	1	\$ 693.20	\$ 693.20	X
Rear Fender(LH) <i>Cut</i>	1	\$ 1,768.30	\$ 1,768.30	✓
Rear Fender Inner Panel (LH) <i>HH</i>	1	\$ 1,406.20	\$ 1,406.20	X
Rear Fender SHIELD REAR PIECE (LH) <i>HH</i>	1	\$ 173.60	\$ 173.60	X
Rear Fender SHIELD Frt Piece (LH) <i>HH</i>	1	\$ 165.50	\$ 165.50	X
Rear Fender Air-Duct (LH) <i>HH</i>	1	\$ 87.30	\$ 87.30	X
Rear Fender Trim Board (LH) <i>HH</i>	1	\$ 788.75	\$ 788.75	X
Fuel Lid Cover LH <i>SVC</i>	1	\$ 83.30	\$ 83.30	X
FUEL LID GARNISH COVER <i>HH</i>	1	\$ 361.20	\$ 361.20	X
REAR FENDER TRIM BOARD TOP GARNISH (LH) <i>HH</i>	1	\$ 167.90	\$ 167.90	X
Assy BSD Blind Spot Radar (LH) <i>HH</i>	1	\$ 1,625.00	\$ 1,625.00	X
Rear Tyre Rim (LH) <i>2 distal</i>	1	\$ 1,124.20	\$ 1,124.20	2.✓
Rear Wheel Hup-Cap (LH) <i>Cut Bt</i>	1	\$ 346.40	\$ 346.40	✓
Rear Wheelbearing & Hub assy <i>2 Dist</i>	1	\$ 554.00	\$ 554.00	2.✓
Rear Trailing Arm(LH) <i>2 distal</i>	1	\$ 265.40	\$ 265.40	2.✓
Rear Assist (LH) <i>2 distal</i>	1	\$ 227.90	\$ 227.90	2.✓
Rear shock Absorber(LH) <i>2 distal</i>	1	\$ 230.50	\$ 230.50	2.✓
Rear Shock Absorber Mounting (LH) <i>HH</i>	1	\$ 133.10	\$ 133.10	X
Rear Absorber stopper (LH) <i>HH</i>	1	\$ 137.60	\$ 137.60	X
Rear Absorber Cover (LH) <i>HH</i>	1	\$ 175.60	\$ 175.60	X
Rear Crossmember <i>HH</i>	1	\$ 1,468.70	\$ 1,468.70	X
Stabilizer Bar <i>HH</i>	1	\$ 387.30	\$ 387.30	X
Stabilizer Link (LH) <i>HH</i>	1	\$ 147.30	\$ 147.30	X
Rear Upper Arm(LH) <i>2 distal</i>	1	\$ 239.50	\$ 239.50	2.✓
Rear Lower Arm(LH) <i>2 distal</i>	1	\$ 393.10	\$ 393.10	2.✓
Rear Knuckle Arm (LH) <i>2 distal</i>	1	\$ 538.10	\$ 538.10	2.✓
7958.70				
SUB TOTAL			\$ 17,789.35	
LESS 20%			\$ 3,557.87	
6366.96			\$ 14,231.48	
DISCOUNTED TOTAL				
Rear Door Tel No.Sticker(LH) <i>Hec</i>	SN 1	\$ 10.00	\$ 10.00	✓
Rear Door Comfortdelgro & Apps Sticker(LH) <i>Hec</i>	SN 1	\$ 80.00	\$ 80.00	✓

SPARE TYRE PANEL TOP COVER SILICON HH	SN	1	\$ 250.00	\$ 250.00	X
Rear Tyre(LH) HH	SN	1	\$ 216.00	\$ 216.00	X
90.00					
SUB TOTAL				\$ 556.00	
Labour Charge					
Panel Beating					
Spray Painting Charge	1		\$1,400.00	\$1,400.00	800
Wiring Charge	1		\$1,200.00	\$1,200.00	700
Tuff Kote	1		\$160.00	\$160.00	30
Towing Charge	1		\$140.00	\$140.00	40
Remove/Refix Undercarriage (RR)	1		\$80.00	\$80.00	HH
Re-set Rear ABS System	1		\$400.00	\$400.00	150
Transfer of Door Mechanism REAR	1		\$400.00	\$400.00	HH
Re-set Rear Power Window System	1		\$80.00	\$80.00	60
Four Wheel Alignment	1		\$200.00	\$200.00	HH
Remove/Refix Undercarriage (Frt)	1		\$120.00	\$120.00	60
Diagnostic & Resetting To Erase Fault Code	1		\$400.00	\$400.00	HH
			\$550.00	\$550.00	180
TOTAL LABOUR				\$5,130.00	
ESTIMATE TOTAL				\$ 19,917.48	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

02/10/2020 e 170km

Not Antenna
Part by Part.

7 days

LKK Auto

8

Photo after
reflex with
damaged parts.

8476.96

Supp 696.32

7/P 9173.28

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR SUPPLEMENTARY

DATE: 6-Oct-20

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC 3379 C (S)

INSURANCE: Chin Te ping

Description	Qty	List Price	Amount
Tail Lamp(LH) <i>monny work</i>	1	\$ 870.40	\$ 870.40
SUB TOTAL			\$ 870.40
LESS 20%			\$ 174.08
DISCOUNTED TOTAL			\$ 696.32

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Wan

2kk Auto

8