

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 05 Oct 2020

## **Preliminary Advice**

Vehicle No	: SLC7275U	Accident Date	: 22/09/2020
Make	: TOYOTA WISH	Policy No.	: DMHCSNA00004172001
Assignment Date	: 01/10/2020	Excess	: S\$1,250.00
Date of Inspection	: 02/10/2020	Est. Duration of Repair	: 28 days
Inspection At	: Goldbell Engineering Pte Ltd (Tuas) 10 Tuas Ave 18 Singapore 638894		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,000.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	TOTAL LOSS
Total	:S\$	TOTAL LOSS
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	5,000.00
COE / PARF Rebate	:S\$	3,045.00
Salvage Value	:S\$	
Margin for Repair	:S\$	1,955.00

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :