



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2104004

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 09/06/2021
Reference CC6/CTI20010576/Dea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 1353A
Insured Veh. SGK 2176Y
Claim No. SNM20D203646
Policy No. DMHCSNA00002692000
Accident Date 30/09/2020
Inspection Date 02/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20010576/Dea3q2 Date: 09/06/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGK 2176Y	Veh. Inspected	SHA 1353A
	Policy No.	DMHCSNA00002692000	Coverage (\$)	0.00
	Claim No.	SNM20D203646	Excess (\$)	0.00
	Assign From		Assign Date	02/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTDKB3FU203562916	Colour	BLUE
	Odometer	326969 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DAVANTI	5 mm
	L/H Front Tyre	195/65 R15	DAVANTI	5 mm
	R/H Rear Tyre	195/65 R15	DAVANTI	5 mm
	L/H Rear Tyre	195/65 R15	DAVANTI	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/09/2020	Inspection Date	02/10/2020
	Survey held at	Blk 9 Sector C #01-42, Sin Ming Industrial Estate		
	Repairer	BIFROST AUTO PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1353A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TRUNK LID COVER	BENT / DENTED	1,126.60	1,126.60
1	REAR TRUNK LID LOCK	DAMAGED	457.90	457.90
1	REAR TRUNK LID COVER TRIM BOARD	NOT NECESSARY	216.50	-
1	BOOT LID TRIMBOARD ,CENTRE	NOT NECESSARY	159.60	-
2	BOOT LID TRIMBOARD SIDE (LH/RH) @\$92.50	NOT NECESSARY	185.00	-
1	BOOT LID TRIMBOARD REAR	NOT NECESSARY	124.80	-
1	BOARD ASSY ,BACK DOOR TRIM	NOT NECESSARY	354.40	-
1	GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	CUT / DENTED	896.30	896.30
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	52.90	52.90
1	REAR TRUNK LID STRIKER	TO REPAIR SEE LABOUR	98.70	-
2	REAR TRUNK LID HINGE (LH/RH) @\$189.50	NOT NECESSARY	379.00	-
2	REAR TRUNK LID ABSORBER (LH/RH) @\$287.50	NOT NECESSARY	575.00	-
2	REAR TRUNK LID ABSORBER BRACKET (LH/RH) @ \$127.90	NOT NECESSARY	255.80	-
2	REAR TRUNK LID STOPPERS (LH/RH) @\$84.80	NOT NECESSARY	169.60	-
1	REAR BUMPER	DENTED	458.60	458.60
1	REAR BUMPER REINFORCEMENT	DENTED	318.80	318.80
1	REAR BUMPER LOWER COVER	DENTED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	112.70	-
1	REAR BUMPER TOWING COVER	CUT	82.70	82.70
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
2	REAR BUMPER UPPER STOPPER (LH/RH) @\$76.40	NOT NECESSARY	152.80	-
1	ARM SUB-ASSY ,REAR BUMPER ,RH	NOT NECESSARY	139.60	-
1	REAR BUMPER UNDER SIDE COVER (RH)	NOT NECESSARY	232.00	-
1	SEAL ,REAR BUMPER SIDE ,RH	NOT NECESSARY	148.40	-
1	SEAL ,REAR BUMPER SIDE ,LH	NOT NECESSARY	148.40	-
1	REAR BUMPER UNDER SIDE COVER (LH)	NOT NECESSARY	232.00	-
1	ARM SUB-ASSY ,REAR BUMPER ,LH	NOT NECESSARY	139.60	-

Report Ref No. CC6/CTI20010576/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL LAMP ASSY (UPPER)	CRACKED	557.90	557.90
1	TAIL LAMP ASSY (LOWER)	CRACKED	548.40	548.40
1	TAIL LAMP QUARTER PANEL	NOT NECESSARY	216.00	-
1	TAIL LAMP SIDE COVER	NOT NECESSARY	256.00	-
2	REAR TAILLAMP GUIDE -WHITE @\$95.30	NOT NECESSARY	190.60	-
1	REAR END PANEL	NOT NECESSARY	602.10	-
1	REAR END PANEL GARNISH	MTG DEFORMED	161.80	161.80
1	REAR SPARE TYRE PANEL	NOT NECESSARY	667.70	-
1	REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	NOT NECESSARY	101.40	-
2	REAR FIBER TOOL BOX TRIM (LH/RH) @\$598.00	NOT NECESSARY	1,196.00	-
1	REAR FIBER TOOL BOX CENTER	NOT NECESSARY	186.20	-
1	SPARE TYRE LOCK NUT	NOT NECESSARY	88.40	-
1	SPARE TYRE LOCK NUT BRACKET	NOT NECESSARY	113.50	-
2	SPARE TYRE SIDE PANEL (LH/RH) @\$196.50	NOT NECESSARY	393.00	-
1	BONNET	DENTED / BENT	950.50	950.50
1	INSULATOR ,HOOD	NOT NECESSARY	398.10	-
10	INSULATOR CLIPS	NOT NECESSARY	36.80	-
1	BONNET CABLE	NOT NECESSARY	83.20	-
1	BONNET HINGE (RH)	BENT	87.70	87.70
1	BONNET HINGE (LH)	BENT	87.70	87.70
1	BONNET LOCK	BENT	132.60	132.60
1	CATCH ,HOOD AUXILIARY HOOK	NOT NECESSARY	8.60	-
1	RADIATOR GRILLE	CRACKED / DEFORMED	438.00	438.00
1	RADIATOR GRILLE EMBLEM	BENT	88.00	88.00
1	FRONT BUMPER COVER	DENTED	499.90	499.90
1	FRONT BUMPER REINFORCEMENT	BENT	696.40	696.40
1	FRONT BUMPER REINFORCEMENT ABSORBER	NOT NECESSARY	115.70	-
1	FRONT BUMPER LOWER REINFORCEMENT	NOT NECESSARY	364.20	-
1	FRONT BUMPER LOWER REINFORCEMENT BRACKET	NOT NECESSARY	330.00	-
2	FRONT SIDE MEMBER REINFORCEMENT PANEL (LH/RH) @\$320.70	NOT NECESSARY	641.40	-
1	FRONT SIDE MEMBER SIDE COVER	NOT NECESSARY	172.50	-
1	FRONT BUMPER SPONGE	TORN	78.80	78.80

Report Ref No. CC6/CTI20010576/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER LOWER GRILLE	DEFORMED / CRACKED	148.60	148.60
1	LAMP ASSY ,FOG, RH	MTG CRACKED	920.00	920.00
1	LAMP ASSY ,FOG, LH	MTG CRACKED	920.00	920.00
1	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRONT BUMPER SIDE RETAINER	NOT NECESSARY	77.00	-
1	FRONT LOWER PANEL	NOT NECESSARY	320.65	-
2	FRONT LOWER SIDE RAIL (LH/RH) @\$230.80	NOT NECESSARY	461.60	-
1	FRONT UNDER COVER	NOT NECESSARY	180.80	-
1	FRONT BUMPER TOP GARNISH	NOT NECESSARY	225.40	-
1	COVER ,FRONT BUMPER HOLE, RH	NOT NECESSARY	28.38	-
1	COVER ,FRONT BUMPER HOLE, LH	NOT NECESSARY	28.38	-
1	ABSORBER ,FRONT BUMPER ,LOWER	NOT NECESSARY	127.70	-
1	UNIT ASSY ,HEADLAMP ,LH (LED)	BROKEN	3,455.00	2,637.60
1	HEADLAMP ECU	NOT NECESSARY	682.60	-
1	HEAD LAMP PANEL (LH)	BENT	240.10	240.10
1	TOP PANEL CENTRE	BENT	364.98	364.98
1	TOP PANEL SIDE (LH)	BENT	14,590.00	145.90
1	BRACE PANEL	NOT NECESSARY	75.20	-
1	RADIATOR ASSY	BENT	1,841.80	1,841.80
1	COOLANT	NOT NECESSARY	45.00	-
1	CONDENSER ASSY ,W/RECEIVER	BENT	1,336.60	1,336.60
1	UNIT ASSY ,HEADLAMP RH (LED) (ADDITIONAL)	MTG BROKEN	3,455.00	2,637.60
1	HEAD LAMP PANEL (RH) (ADDITIONAL)	BENT	240.10	240.10
1	TOP PANEL SIDE (ADDITIONAL)	BENT	145.90	145.90
1	AIR DUCT NO.2 (ADDITIONAL)	MTG CRACKED	129.40	129.40
2	TAIL LAMP ASSY (UPPER) (LH/RH) @\$557.90 (ADDITIONAL)	O/S CRACKED / N/S REPEATED	1,115.80	557.90
2	TAIL LAMP ASSY (LOWER) (LH/RH) @\$548.40 (ADDITIONAL)	O/S CRACKED / N/S REPEATED	1,096.80	548.40
	LESS 20% DISCOUNT		-10,133.88	-
	LESS 25% DISCOUNT		-	-5,311.55
			40,535.51	15,934.63

Report Ref No. CC6/CTI20010576/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TRUNK LOWER W/S MOULDING (SN)	NECESSARY	180.00	180.00
1	REAR LOWER W/S SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR WINDSCREEN MOULDING (SN)	NECESSARY	160.00	160.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR NO.PLATE WITH COVER (SN)	NOT NECESSARY	45.00	-
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO.STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NOT FITTED	50.00	-
1	FRONT NO.PLATE TRIM COVER (SN)	BENT	30.00	20.00
1	FRONT NO.PLATE GARNISH (SN)	BENT	99.00	99.00
1	FRONT BUMPER LOGO (SN)	NOT FITTED	87.10	-
1	FRONT NO.PLATE (SN)	BENT	25.00	25.00
			1,003.80	811.70
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TRUNK LID STRIKER.		1,600.00	900.00
	SPRAY PAINTING CHARGE.		1,400.00	900.00
	WIRING CHARGE.		160.00	30.00
	TUFF KOTE.		160.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX REVERSE SENSOR .		120.00	40.00
	REMOVE/REFIX RADIATOR .		90.00	50.00
	REMOVE/REFIX AIRCON & REFILL GAS.		130.00	80.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	550.00	-
			4,290.00	2,040.00
	GRAND TOTAL		45,829.31	18,786.33

Report Ref No. CC6/CTI20010576/Dea3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			15,000.00
---	--	--	------------------

Report Ref No. CC6/CTI20010576/Dea3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 1353A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 1353A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 1353A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

