

ASS. REC. BY: Marcus

REF:

CS/SMO200/2577/4ydz

QNTD2002873/AGC

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Smith LTA 18808 rep 16k home video
Nett 46192

9/10/20 L/S 4200 confirmed w. h. Am. (Red \$5252-40, 55%)
9/10/20 Sent Preli by email

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

9/10/20 Typist

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum I.B.I. (\$) \$4200/-

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

Submit to ins

Not Authorized
Date
2/10/20
2/5 = 4200 / 3d

VEHICLE No: SFZ 9467U

1PC	FRONT BUMPER	1215.32
1PC	FRONT BUMPER REINFORCEMENT	388.20
1PC	FRONT BUMPER SIDE RETAINER O/S	65.50
1PC	FRONT BUMPER NOZZLE COVER	
1PC	FRONT BUMPER NOZZLE	
1PC	FRONT BUMPER FOG LAMP O/S	
1PC	FRONT BUMPER PDC SENSOR O/S	199.00
1PC	FRONT BUMPER INNER RETAINER O/S	
1SET	FRONT BUMPER CLIPS	
1PC	HEADLAMP O/S	2180.00
1PC	FRONT FENDER O/S	
1PC	FRONT FENDER INNERSHIELD O/S	
1SET	FRONT FENDER INNERSHIELD CLIPS O/S	

2.1	\$1,886.50	/
2.2	\$655.20	/
one	\$82.80	/
20.1	\$45.00	/
one	\$288.20	/
one	\$450.50	/
Should	\$235.00	/
one	\$188.20	/
111	\$50.00	/
holder one	\$2,880.20	/
11	\$661.30	X
11	\$199.50	X
11	\$50.00	X
	\$7,672.40	

(10 %)

TO CHECK WIRING
TO SPRAY RUST PROOFING
TO CONDUCT WHEEL ALIGNMENT
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	20
11	\$50.00	X
11	\$80.00	X
	\$800.00	280
	\$800.00	400

TOTAL \$9,452.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

5069.82
102
8-4562.92
2-700.00
5262.82
4210.