

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20010586/UPA3Q2  
**Date:** 30/03/2021

### REFERENCE

|                       |                                      |                      |              |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer:     | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:           | 2070062951   |
| Claimant Vehicle No : | SFH9119U                             | Insured Vehicle No : | GBB3258U     |
| Date of Loss:         | 01/10/2020                           | Nature of Claim:     | TP           |
|                       |                                      | Claim No:            | 6834572490SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                           |             |                   |
|-----------------------------|-------------------------------------------|-------------|-------------------|
| Reg No:                     | SFH9119U                                  | Engine No:  | A2050975N20B20A   |
| Make & Model:               | BMW 428i, 2.0 D/AB SR HID NAV M SPORT (A) | Chassis No: | WBA4A52030GA69359 |
| Reg. Date:                  | 30/07/2015 (Man. Year: 2014)              | Odometer:   | 80142 km          |
| Colour:                     | Black/White                               |             |                   |
| Engine Capacity:            | 1997 cc                                   |             |                   |
| Market Value/New Car Price: | N/A                                       |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>         |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 245/35Z R19   | Rear Tyre Size:  | 295/30Z R19   |
| Front Left Side:  | Habilead 6 mm | Rear Left Side:  | Habilead 6 mm |
| Front Right Side: | Habilead 6 mm | Rear Right Side: | Habilead 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                                    | Repairer's       | Adjuster's       | Difference       | Diff %       |
|---------------------------------------------------|------------------|------------------|------------------|--------------|
| Parts                                             | 30,253.31        | 17,412.67        | 12,840.64        | 42.44        |
| Miscellaneous Items                               | 0.00             | 0.00             | 0.00             |              |
| Labour                                            | 3,500.00         | 2,080.00         | 1,420.00         | 40.57        |
| Paintwork Labour                                  | 0.00             | 0.00             | 0.00             |              |
| Towing                                            | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>               | <b>33,753.31</b> | <b>19,492.67</b> | <b>14,260.64</b> | <b>42.25</b> |
| <b>Approved Total (Overridden) (S\$)</b>          |                  | <b>15,500.00</b> |                  |              |
| <b>Nett Amount (S\$)</b>                          | <b>33,753.31</b> | <b>15,500.00</b> | <b>18,253.31</b> | <b>54.08</b> |
| <b>+ Loss of Use (14.0 x S\$110.00/day) (S\$)</b> |                  | 1,540.00         |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                     |                  | 7.45             |                  |              |
| <b>+ Other Costs (S\$)</b>                        |                  | 180.00           |                  |              |
| <b>Nett Liability (S\$)</b>                       |                  | <b>17,227.45</b> |                  |              |
| <b>Global Sum Settlement (S\$)</b>                |                  | <b>17,200.00</b> |                  |              |

### INSPECTION

|                             |            |               |                                                                                 |
|-----------------------------|------------|---------------|---------------------------------------------------------------------------------|
| Date of Assignment:         | 02/10/2020 |               |                                                                                 |
| Date Inspected:             | 02/10/2020 | Inspected At: | ZOOM AUTOWERKS PTE LTD<br>130 Bedok Reservoir Road<br>#08-1339 Singapore 470130 |
| Estimated Period of Repair: | 10.0 days  |               |                                                                                 |

---

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                                          | Condition            | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------------------------|----------------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER M-SERIES                                | Distorted            | 2,900.00 FL | *1,850.00 FL |
| 2   | 2   |          | *REAR BUMPER SIDE GUIDE                              | Not Necessary        | 224.40 FL   | *- FL        |
| 3   | 1   |          | *REAR BOOT INNER TRIM                                | Cracked              | 191.20 FL   | *191.20 FL   |
| 4   | 1   |          | *REAR BUMPER CENTRE INNER BRACKET                    | Cracked              | 320.40 FL   | *320.40 FL   |
| 5   | 1   |          | *REAR BUMPER REINFORCEMENT                           | Bent                 | 880.00 FL   | *715.00 FL   |
| 6   | 4   |          | *REAR BUMPER SENSOR (ORI)                            | Shorted (2 PCS ONLY) | 1,452.40 FL | *470.00 FL   |
| 7   | 1   |          | *REAR BUMPER INNER PLATE                             | Cracked              | 115.00 FL   | *115.00 FL   |
| 8   | 1   |          | *REAR BUMPER TOW GARNISH                             | Torn                 | 110.00 FL   | *60.00 FL    |
| 9   | 1   |          | *SET REAR BUMPER CLIPS                               | Necessary            | 60.00 FL    | *60.00 FL    |
| 10  | 1   |          | *REAR BOOTLID PANEL                                  | Badly Dented         | 1,553.00 FL | *1,553.00 FL |
| 11  | 1   |          | *REAR BOOTLID INNER LOCK                             | Twisted              | 495.00 FL   | *495.00 FL   |
| 12  | 1   |          | *REAR BOOTLID LOGO                                   | Necessary            | 198.00 FL   | *120.00 FL   |
| 13  | 1   |          | *REAR BOOTLID WEATHER STRIP                          | Twisted              | 468.00 FL   | *365.00 FL   |
| 14  | 2   |          | *REAR BOOTLID LAMP                                   | Cracked              | 1,566.00 FL | *1,240.00 FL |
| 15  | 2   |          | *REAR TAILLAMPS                                      | Cracked              | 1,972.00 FL | *1,490.00 FL |
| 16  | 1   |          | *REAR END PANEL                                      | Dented               | 789.00 FL   | *789.00 FL   |
| 17  | 1   |          | *REAR END PANEL TOP GARNISH                          | Not Necessary        | 225.00 FL   | *- FL        |
| 18  | 1   |          | *REAR END PANEL TOP GARNISH CLIPS                    | Not Necessary        | 60.00 FL    | *- FL        |
| 19  | 1   |          | *REAR SPARE TYRE TOP BOARD                           | Not Necessary        | 265.40 FL   | *- FL        |
| 20  | 1   |          | *BATTERY CABLE TERMINAL                              | Activated            | 285.00 FL   | *285.00 FL   |
| 21  | 1   |          | *REAR ACCESSORIES -BODY PANEL STICKER (PEARL WHITE)  | Necessary            | 3,500.00 FS | *800.00 FS   |
| 22  | 1   |          | *REAR BUMPER DIFFUSER STICKER STRIP (RED)            | Necessary            | 450.00 FS   | *100.00 FS   |
| 23  | 1   |          | *REAR BUMPER DIFFUSER M-SERIES ACCESSORIES           | Distorted            | 3,200.00 FS | *2,000.00 FS |
| 24  | 1   |          | *REAR BOOTLID PANEL TOP SPOILER M-SERIES ACCESSORIES | Broken               | 2,800.00 FS | *1,000.00 FS |
| 25  | 1   |          | *AKRAPOVIC EXHAUST PIPE ASSY                         | Bent / Cracked       | 6,200.00 FS | *3,500.00 FS |
| 26  | 1   |          | *AKRAPOVIC EXHAUST TIP                               | Bent                 | 520.00 FS   | *300.00 FS   |
| 27  | 1   |          | *REAR END PANEL SEALANT                              | Necessary            | 80.00 FS    | *50.00 FS    |
| 28  | 1   |          | *REAR NUMBER PLATE W/BASE CHROME                     | Scratched            | 80.00 FS    | *50.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                        |                  |                  |
|--------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$)</b>                                  | <b>30,959.80</b> | <b>17,918.60</b> |
| <b>- List Item Discount on L Items 5.00/5.00% (\$)</b> | 706.49           | 505.93           |
| <b>Total Parts (\$)</b>                                | <b>30,253.31</b> | <b>17,412.67</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                                | Lab.Type | Repairer's      | Amount          |
|-------------------------|------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>     |                                                            |          |                 |                 |
| 1                       | TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS     | New      | 1,400.00        | 800.00          |
| 2                       | TO PUTTY ,SRPAY PAINT ON AFFECTED ACCIDENT AREAS           | New      | 1,200.00        | 1,000.00        |
| 3                       | TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING                | New      | 150.00          | 30.00           |
| 4                       | TO REMOVE & INSTALL REAR BOOTLID COMPONENTS TRIM & GARNISH | New      | 150.00          | 60.00           |
| 5                       | TO REMOVE & INSTALL REAR FENDERS TRIM GARNISH              | New      | 150.00          | 80.00           |
| 6                       | TO CONDUCT WATER LEAKAGE TEST                              | New      | 150.00          | 0.00            |
| 7                       | TO REMOVE ,INSTALL & RE-POSITION REVERSE SENSOR            | New      | 150.00          | 50.00           |
| 8                       | TO RUST RPOOF AFFECTED AREAS                               | New      | 150.00          | 60.00           |
| Gross Labour Cost (S\$) |                                                            |          | <b>3,500.00</b> | <b>2,080.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >