



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0719/2020/NS
DATE : 1-Oct-20
WIP : 51481

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

3 days ok - 02/12/2020 - Carrine

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR ROCKY YULIANTO SAPUTRA
ADDRESS : BLK 88 TELOK BLANGAH HEIGHTS
#19-357
SINGAPORE 100088
TELEPHONE : HP +65 90678100
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900020101
VEHICLE NO : SMJ 3626 T
MODEL CODE : AUDI A3 SPORTSBACK 1.0 TF
MODEL YEAR : 28/2/2019
ENGINE NO : CHZ C26035
CHASSIS NO : WAUZZZ8V0KA028716
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Sep-20
PLACE OF ACCIDENT : PIE TOWARDS TUAS(AFTER SIMEI)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 3626 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	\$ 280.00
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED.	\$ 1,000.00	\$ 500.00
3	TO RESPRAY FRONT BUMPER.	\$ 1,100.00	\$ 550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 2,572.00	\$ 1,522.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3626 T

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 1,842.00	\$ 1,473.60
2	FRONT BUMPER FIXING PARTS		\$ 185.00	
3	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 76.00	
4	FRONT BUMPER GRILLE - CENTRE		\$ 159.00	\$ 126.80
5	FRONT BUMPER GRILLE CLOSING ELEMENT - LOWER CENTRE		\$ 293.00	
6	FRONT BUMPER CLOSING ELEMENT- LH / RH	2	\$ 586.00	
7	RADIATOR GRILLE		\$ 1,406.00	\$ 1,124.80
8	RADIATOR GRILLE CLOSING ELEMENT		\$ 189.00	
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 372.00	\$ 148.40
10	FRONT REINFORCEMENT BEAM		\$ 715.00	
11	FRONT BUMPER FOAM FILLER PIECE		\$ 187.00	
12	FOAM FILLER PIECE COVER		\$ 121.00	
13	AIRCON STICKER	NEC	\$ 8.00	\$ 5.68
14	CAUTION SIGN STICKER	NEC	\$ 14.00	\$ 10.80
15	SIGNAL HORN - LH HIGH TONE		\$ 197.00	
16	SIGNAL HORN - RH LOW TONE		\$ 197.00	
17	LED HEADLIGHT - LH / RH	2	\$ 10,910.00	
18	LIFT CYLINDER - LH / RH	2	\$ 282.00	
19	LIFT CYLINDER HOSE		\$ 67.00	
20	RADIATOR AIR GUIDE - LH / RH	2	\$ 48.00	
SUB TOTAL SPARE PARTS		:	\$ 17,854.00	\$ 2,890.08

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3626 T

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
		c/f		\$	2,890.08
21	RADIATOR AIR GUIDE - UPPER CENTRE		\$ 12.00		
22	BONNET CATCH HOOK		\$ 63.00		
23	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
24	SUNDRIES		\$ 200.00	\$	19.20
TOTAL SPARE PARTS		:	\$ 18,189.00	\$	2,969.28
TOTAL LABOUR CHARGES		:	\$ 2,572.00	\$	1,522.00
GRAND TOTAL		:	\$ 20,761.00	\$	4,491.28

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

b1-10/11/20