

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
SOM	SOMPO INSURANCE SINGAPORE PL			CS3/SMO20010596	/KQsd3e2	
	AFFLES PLACE # ER SINGAPORE	05-01/06 SINGAPORE LAND 048623	Date:	07-10-2020		
			Code:	SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	YN 7525L	Veh. Inspected		SKE 5765L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2002875/THE	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		02/10/2020	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA CAMRY 2.0 AT	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	MR053BK4107027025	Colour		WHITE	
	Odometer	234643 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	WEST	LAKE	6 mm	
	L/H Front Tyre	215/60 R16	WEST	LAKE	6 mm	
	R/H Rear Tyre	215/60 R16	WEST	LAKE	6 mm	
	L/H Rear Tyre	215/60 R16	WEST LAKE		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
5. General Information						
	Accident Date	01/10/2020	Inspec	ct Date / Time	02/10/2020 ( 01:51 PM )	
	Survey held at	160 SIN MING DRIVE #05-17				
	Repairer	Repairer HIAP LEK AUTOMOBILE TRADING				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					

Report Ref No. CS3/SMO20010596/KQsd3e2

Inspected By

KONG SENG CHEONG

**Licensed Appraiser** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.