

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Oct 2020 16:54 Edit Reg		07 Oct 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	MOHAMED IQBAL HAIDER ALI, ID: S1668498H		
Main Claimant:	MUHAMMAD FAZIL BIN ZAILANI		
Vehicle Reg. No.:	SJF7884U	Date of Loss:	23/09/2020 12:00 - :59 [147 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SKG1132D	Policy No. (Claimant):	MT/00646812/01
		Excess:	
Repairer:	Garage 13 Pte. Ltd. (HQ) 8 Kaki Bukit Avenue 4, #03-46 Premier, 415875 Kaki Bukit - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 13/10/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJF7884U**
[SKG1132D]
TP

MUHAMMAD FAZIL BIN ZAILANI
Sep 23 2020 12:00PM
[MOHAMED IQBAL HAIDER ALI]
Garage 13 Pte. Ltd.

View

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/10/20 21:44	General View	 Load JPG	☒
2	13/10/20 21:44	General View	 Load JPG	☒
3	13/10/20 21:44	General View	 Load JPG	☒
4	13/10/20 21:44	Odometer Reading	 Load JPG	☒
5	13/10/20 21:44	Chassis Number	 Load JPG	☒
6	13/10/20 21:44	General View	 Load JPG	☒
7	13/10/20 21:44	General View	 Load JPG	☒
8	13/10/20 21:44	General View	 Load JPG	☒
9	13/10/20 21:44	General View	 Load JPG	☒
10	13/10/20 21:44	General View	 Load JPG	☒
11	13/10/20 21:44	General View	 Load JPG	☒
12	13/10/20 21:44	General View	 Load JPG	☒
13	13/10/20 21:44	General View	 Load JPG	☒
14	13/10/20 21:44	General View	 Load JPG	☒
15	13/10/20 21:44	General View	 Load JPG	☒
16	13/10/20 21:44	General View	 Load JPG	☒
17	13/10/20 21:44	General View	 Load JPG	☒
18	13/10/20 21:44	General View	 Load JPG	☒
19	13/10/20 21:44	General View	 Load JPG	☒
20	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
21	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
22	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
23	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
24	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
25	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
26	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
27	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
28	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
29	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
30	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
31	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
32	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
33	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
34	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
35	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
37	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
38	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
39	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
40	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
41	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
42	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
43	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
44	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
45	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
46	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
47	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
48	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
49	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
50	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
51	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
52	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
53	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
54	13/10/20 21:45	Photo After Spray	 Load JPG	☒
55	13/10/20 21:45	Photo After Spray	 Load JPG	☒
56	13/10/20 21:45	Photo After Spray	 Load JPG	☒
57	13/10/20 21:45	Photo After Spray	 Load JPG	☒
58	13/10/20 21:45	Photo After Spray	 Load JPG	☒
59	13/10/20 21:45	Photo After Spray	 Load JPG	☒
60	13/10/20 21:45	Photo After Spray	 Load JPG	☒
61	13/10/20 21:45	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/10/20 15:44	ACKNOWLEDGEMENT EMAIL TO III DD 02.10.2020	 Load PDF	
2	02/10/20 15:44	TP GIA REPORT	 Load PDF	
3	05/10/20 09:19	Status of Driving Licence DD 05.10.2020	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/10/20 08:30	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III20010600/EYF3S2**Date:** 30/10/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SJF7884U**Insured Vehicle No :** SKG1132D

Date of Loss: 23/09/2020

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJF7884U**

Make & Model: HONDA CITY, 1.5 CVT (A)

Engine No: L15A26801447

Reg. Date: 11/06/2008 (Man. Year: 2007)

Chassis No: MRHGD86908P010114

Colour: Black

Odometer: 132057 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/10/2020

Date Inspected: 08/10/2020 Inspected At:

Garage 13 Pte. Ltd
8 Kaki Bukit Avenue 4, #03-46 Premier
Singapore 415875

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE**Manager:** YVONNE WONG YIN CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

10/30/2020

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2020)
Parts:	143	HONDA CITY 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF7884U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >