



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

GREAT AMERICAN INSURANCE COMPANY 3 Temasek Ave., #16-01 Centennial Tower Singapore 039190 ATTN. : FAX :		NAME : Mr Loo Yong Keong, Terence ADDRESS : 22 Ghim Moh Link #15-210 Singapore 271022 TEL : 97689355		WIP : 19854 EXCESS : DATE: 30-Sep-20	
VEH NO :	SLG9362S	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6BM42A8G0344829	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 3	DATE REG. :	19-Oct-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER <i>de</i>	1	MBPD8-50-221ABB	1128.60	996.70
2	BRACKET CENTER <i>? X Svc</i>	1	MKD53-50-251		5.40
3	GROMMET, REAR BUMPER <i>nee</i>	4	MBHN1-50-0Z1A		10.80
4	RIVET, REAR BUMPER <i>nee</i>	4	MBBM4-50-355		18.00
5	FASTENER, REAR BUMPER <i>nee</i>	4	MB45A-56-146A		12.00
6	CLIP, REAR BUMPER <i>nee</i>	2	MGJ21-50-049		6.80
7	CLIP, REAR BUMPER <i>nee</i>	4	MC274-50-133		14.80
8	RETAINER CENTER, SENSOR <i>X Svc</i>	2	MKD47-67-UC5A50		36.40
9	SENSOR CENTER, ULTRASONIC <i>X Svc</i>	2	MKD47-67-UC1 50		407.20
10	TAPE PROTECTOR, REAR BUMPER <i>nee</i>	3	MG51D-50-EM1A		25.80
11	REAR REINFORMENT <i>? bt</i>	1	MB45A-50-260		564.20
12	GASKET LHS, TAILLAMP <i>nee</i>	1	MBHN1-51-163		22.00
13	GASKET RHS, TAILLAMP <i>nee</i>	1	MBHN1-51-153		22.00
14	ANTENNA <i>X Svc</i>	1	MKD47-67-6NXA		111.10
15	CLIP, ANTENNA <i>X nn</i>	1	MKD45-67-6NYA		2.70
TOTAL PARTS					2,255.90
TOTAL PARTS COST					2,255.90
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		660	1,550.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.		630	1,575.00
3	MZ-BR-REVSSEN	TO TRANSFER REVERSE SENSORS.		280	330.00

4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150 /	250.00
5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	XM	250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180 /	350.00
7	MZ-BR-SUNDRI	SUNDRIES.	NETT	100.00 20 /

TOTAL LABOUR	-	4,505.00
TOTAL PARTS	-	2,255.90
TOTAL	-	6,760.90
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	-
GST 7%	-	-
GRAND TOTAL	-	-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR

TRANS EUROKARS PTE LTD

Authorised Signature

Rasul
Hp 90010068

3 days

06/10/2020

@1100

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: