



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2101431

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 09/03/2021
Reference CC4/CTI20010608/T1gs3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMA 3686S
Insured Veh. GBD 9465M
Claim No. SNM20D203652
Policy No. DMCVSNW00067982001
Accident Date 30/09/2020
Inspection Date 05/10/2020

Description	Total
Survey Inspection	350.00
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC4/CTI20010608/T1gs3q2 Date: 09/03/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 9465M	Veh. Inspected	SMA 3686S
	Policy No.	DMCVSNW00067982001	Coverage (\$)	0.00
	Claim No.	SNM20D203652	Excess (\$)	0.00
	Assign From	ALBERT	Assign Date	02/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	KIA FORTE K3	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	KNAFJ411MJ5761916	Colour	WHITE
	Odometer	25308 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	NEXEN	6 mm
	L/H Front Tyre	195/65 R15	NEXEN	6 mm
	R/H Rear Tyre	195/65 R15	NEXEN	6 mm
	L/H Rear Tyre	195/65 R15	NEXEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/09/2020	Inspection Date	05/10/2020
	Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 3686S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEADLAMP ASSY RH	* CHECK	810.00	-
1	RADIATOR GRILLE (NPA)	* CHECK	-	-
1	FRONT BUMPER	CRACKED	631.00	631.00
1	FRONT BUMPER TOP RUBBER	NOT NECESSARY	28.00	-
1	FRONT BUMPER LOGO	NECESSARY	38.00	38.00
1	FRONT BUMPER RETAINER RH	DEFORMED	18.00	18.00
1	FRONT BUMPER AIR GRILLE RH	* CHECK	15.00	-
1	FRONT BUMPER LOWER GRILLE-CENTER	* CHECK	75.00	-
1	FRONT BUMPER SPONGE	* CHECK	84.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	496.00	-
10	FRONT BUMPER CLIPS @\$3.50	NECESSARY	35.00	35.00
1	FRONT FENDER COWLING RH	TORN	88.00	88.00
10	FRONT FENDER COWLING CLIPS @\$3.50	NECESSARY	35.00	35.00
1	SUPPORT PANEL (NPA)	* CHECK	-	-
	LESS 10% DISCOUNT		-235.30	-84.50
			2,117.70	760.50
	<u>LABOUR</u>			
	TO KNOCK AND STRAIGHTEN SUPPORT PANEL, REMOVE AND REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION.		400.00	250.00
	SPRAY PAINT FRONT BUMPER, FRONT FENDER RH.		350.00	250.00
			750.00	500.00
	GRAND TOTAL		2,867.70	1,260.50
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$885.60 NETT)			1,260.50

Report Ref No. CC4/CTI20010608/T1gs3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 3686S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

