

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20010609/UVF3E2

Date: 12/10/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29128317AV2

Claimant Vehicle No : SLH4108M

Insured Vehicle No : SMM1183B

Date of Loss: 27/09/2020

Nature of Claim: TP

Claim No: 629164

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH4108M

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZRR961796

Reg. Date: 01/11/2016 (Man. Year: 2016)

Chassis No: JTDKB3FU503537301

Colour: Silver

Odometer: 130765 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,880.84	2,749.06	3,131.78	53.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,260.00	1,020.00	44.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,160.84	4,009.06	4,151.78	50.87
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	8,160.84	3,200.00	4,960.84	60.79

INSPECTION

Date of Assignment: 02/10/2020

Date Inspected: 05/10/2020 Inspected At:

Siang Hui Motor Works (HQ)

3006 Ubi Road 1, #01-338

Singapore 408700

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Oct 2020)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH4108M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Badly Dented	1,300.70 FL	*1,300.70 FL
2	1		*FRONT DOOR W/STRIP O/S	Necessary	116.30 FL	*116.30 FL
3	1		*FRONT SIDE MIRROR ASSY	Broken	1,436.00 FL	*1,023.89 FL
4	1		*SIDE MIRROR COVER	Cut	113.20 FL	*98.07 FL
5	1		*FRONT FENDER O/S	Dented / Bent	977.80 FL	*606.36 FL
6	1		*FRONT BUMPER	Repair	516.00 FL	*- FL
7	1		*SIDE SKIRT GARNISH O/S	Cracked	594.80 FL	*520.10 FL
8	1		*SPORT RIM O/S	Repair	1,837.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,891.80	3,665.42
- List Item Discount on L Items 20.00/25.00% (\$\$)	1,010.96	916.36
Total Parts (\$\$)	5,880.84	2,749.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WHEEL ALIGNMENT	New	80.00	60.00
2	TO SPRAY PAINTING	New	1,100.00	800.00
3	TO REMOVE, REPLACE FRONT DOOR, FRONT FENDER, BUMPER & SIDE SKIRT	New	1,100.00	400.00
Gross Labour Cost (\$\$)			2,280.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >