

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS / MSG20010609/uvf3**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / NS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

08/10/20 LTA \$385902nd door \$1405.23, mirror 1023.808/10/20 conf. rmd 1/5 \$3200 with AH long (Red 4960.28, 61%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 8/10/20-Typist

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS. SI☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format : MerimenLump Sum H.B.: (\$ 3200)

TOTAL

祥輝汽車修理 SIANG HUI MOTOR WORKS

Blk 3006, Ubi Road 1 #01-338, Singapore 408700.

Tel: 67444605 Fax: 67440726

REG. No. 322208/00M

Not Authorised
2/5 \$3200
4/5
Zhurhappu
2/1

Date: 3/10/20

Vehicle No: SLH 4108M To/Of

1	1 PC Front door o/s	2.4/3.00	\$ 1300.70	✓
2	1 PC Front door w/strip. o/s new		\$ 116.30	✓
3	1 PC Front side mirror	1023.89	\$ 1436.00	✓
4	1 PC side mirror cover	98.02	\$ 113.20	✓
5	1 PC Front fender o/s	606.36	\$ 977.80	✓
6	1 PC Front bumper	2	\$ 516.00	X
7	1 PC Side Skirt	520.10	\$ 594.80	✓
			\$ 5054.10	
Less 20% 25%			\$ 1010.82	
			\$ 4043.28	
8	1 PC Sport Rim o/s	2	\$ 1837.00	SNX

Labour charges:-

1)	To check wheel alignment	\$ 80.00	60
2)	To Spray painting	\$ 1100.00	800
3)	To remove, replace front door		
front fender, bumper & side skirt		\$ 1100.00	400

\$ 8160.28

P-3665-42

25%

P-2749-06

L-1260-80

4009-06

LKK Auto Consultants hence notify the Repairer the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: