

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 2-Oct-20

MODEL: HYUNDAI IONIC

INSURANCE: III

VEHICLE NO.: SHA 4778 M

C64/III 20010610/D6c³

Description	Qty	List Price	Amount	
Rear Door (RH) <i>Wt</i>	1	\$ 1,789.90	\$ 1,789.90	✓
Rear Door Trim Board (RH) <i>HH</i>	1	\$ 613.60	\$ 613.60	X
Rear Door Protector (RH) <i>HH</i>	1	\$ 166.20	\$ 166.20	X
Rear Fender (RH) <i>Danda</i>	1	\$ 1,768.30	\$ 1,768.30	✓
Rear Fender SHIELD Frt Piece (RH) <i>HH</i>	1	\$ 165.50	\$ 165.50	X
Rear Fender Air-Duct (RH) <i>HH</i>	1	\$ 87.30	\$ 87.30	X
Rear Fender Trim Board (RH) <i>HH</i>	1	\$ 788.75	\$ 788.75	X
Assy BSD Blind Spot Radar (RH) <i>HH</i>	1	\$ 1,625.00	\$ 1,625.00	X
Rear Tyre Rim (RH) <i>disturb</i>	1	\$ 1,124.20	\$ 1,124.20	X
Rear Wheel Hup-Cap (RH) <i>2 Disturb</i>	1	\$ 346.40	\$ 346.40	✓
Rear Wheelbearing & Hub assy <i>2 Disturb</i>	1	\$ 554.00	\$ 554.00	✓
Rear Trailing Arm (RH) <i>2 Disturb</i>	1	\$ 265.40	\$ 265.40	✓
Rear Assist (RH) <i>2 Disturb</i>	1	\$ 227.90	\$ 227.90	✓
Rear shock Absorber (RH) <i>2 Disturb</i>	1	\$ 230.50	\$ 230.50	✓
Rear Shock Absorber Mounting (RH) <i>HH</i>	1	\$ 133.10	\$ 133.10	X
Rear Absorber stopper (RH) <i>HH</i>	1	\$ 137.60	\$ 137.60	X
Rear Absorber Cover (RH) <i>HH</i>	1	\$ 175.60	\$ 175.60	X
Rear Crossmember <i>HH</i>	1	\$ 1,468.70	\$ 1,468.70	X
Stabilizer Bar <i>HH</i>	1	\$ 387.30	\$ 387.30	X
Stabilizer Link (RH) <i>HH</i>	1	\$ 147.30	\$ 147.30	X
Rear Upper Arm (RH) <i>2 Disturb</i>	1	\$ 239.50	\$ 239.50	✓
Rear Lower Arm (RH) <i>2 Disturb</i>	1	\$ 393.10	\$ 393.10	✓
Rear Knuckle Arm (RH) <i>2 Disturb</i>	1	\$ 538.10	\$ 538.10	✓
7477.30				
SUB TOTAL			\$ 13,373.25	
5981.84				
LESS 20%			\$ 2,674.65	
DISCOUNTED TOTAL			\$ 10,698.60	
Rear Door Tel No. Sticker (RH) <i>Hee</i>	SN 1	\$ 10.00	\$ 10.00	✓
Rear Door Comfortdelgro & Apps Sticker (RH) <i>Hee</i>	SN 1	\$ 80.00	\$ 80.00	✓
Rear Tyre (RH) <i>HH</i>	SN 1	\$ 216.00	\$ 216.00	X
90.00				
SUB TOTAL			\$ 306.00	
Labour Charge				
Panel Beating				
Spray Painting Charge	1	\$1,400.00	\$1,400.00	600/-
Wiring Charge	1	\$1,200.00	\$1,200.00	400/-
Tuff Kote	1	\$140.00	\$140.00	HH
Towing Charge	1	\$160.00	\$160.00	40/-
Remove/Refix Undercarriage (RR)	1	\$80.00	\$80.00	HH
Re-set Rear ABS System	1	\$400.00	\$400.00	150/-
	1	\$400.00	\$400.00	HH

Transfer of Door Mechanism REAR	1	\$80.00	\$80.00	601
Re-set Rear Power Window System	1	\$200.00	\$200.00	44
Four Wheel Alignment	1	\$120.00	\$120.00	601-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	1801
TOTAL LABOUR				
ESTIMATE TOTAL			\$4,730.00	
			\$ 15,734.60	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

05/10/22 @ 0915h

Nkt Andrew

7/P 7561.84

Ryan

6 days

LKK Auto

8

Photo after repair
with damaged
parts.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: