

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0724/2020/NS
DATE : 2-Oct-20
WIP : 51709

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : SEE PEI YUEN(XU PEIYUN)
ADDRESS : BLK 260B ANG MO KIO STREET 21
#20-159
SINGAPORE 562260
TELEPHONE : HP +65 98286757
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070120346
VEHICLE NO : **SMU 1307 U**
MODEL CODE : AUDI A3 SPORTSBACK 1.0 TF
MODEL YEAR : 20/8/2020
ENGINE NO : CHZ C38574
CHASSIS NO : WAUZZZ8V7LA044297
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Oct-20
PLACE OF ACCIDENT : ANG MO KIO AVE 1 & UPPER THOMSON RD JUNCTION



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 1307 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X ✓
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	500 ✓
3	TO RESPRAY FRONT BUMPER.	\$ 900.00	550 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,422.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 1307 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 FRONT BUMPER <i>Rep to a</i>		\$	✓ 1,842.00 +	1473.60
2 FRONT BUMPER FIXING PARTS <i>me</i>		\$	185.00 +	
3 FRONT BUMPER GRILLE - CENTRE <i>me</i>		\$	159.00 +	
4 RADIATOR GRILLE <i>could</i>		\$	1,406.00 ✓	1124.80
5 RADIATOR GRILLE CLOSING ELEMENT ?		\$	CRACKED 189.00 ? ✓	150.80
6 FRONT BUMPER COVER <i>me</i>		\$	121.00 +	
7 FRONT BUMPER FOAM FILLER PIECE <i>me</i>		\$	187.00 +	
8 FRONT REINFORCEMENT BEAM		\$	715.00 +	
9 AIRCON STICKER <i>me</i>	NEC	\$	8.00 +	
10 CAUTION SIGN STICKER	NEC	\$	14.00 +	
11 FRONT NO PLATE <i>Dented</i>	S/N	\$	60.00 ✓	✓
12 SUNDRIES <i>Rec.</i>		\$	300.00 ?	16.40
TOTAL SPARE PARTS	:	\$	5,186.00	
TOTAL LABOUR CHARGES	:	\$	2,422.00	
GRAND TOTAL	:	\$	7,608.00	

ALL CHARGES ARE INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

 **PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *05/10/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorized, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT