

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0724/2020/NS  
DATE : 2-Oct-20  
WIP : 51709

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.**

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120

**ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**  
**TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME : SEE PEI YUEN(XU PEIYUN)  
ADDRESS : BLK 260B ANG MO KIO STREET 21  
#20-159  
SINGAPORE 562260  
TELEPHONE : HP +65 98286757  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 2070120346  
VEHICLE NO : **SMU 1307 U**  
MODEL CODE : AUDI A3 SPORTSBACK 1.0 TF  
MODEL YEAR : 20/8/2020  
ENGINE NO : CHZ C38574  
CHASSIS NO : WAUZZZ8V7LA044297  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 1-Oct-20  
PLACE OF ACCIDENT : ANG MO KIO AVE 1 & UPPER THOMSON RD JUNCTION



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 1307 U**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00 X	
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ <del>1,050.00</del> 500	
3	TO RESPRAY FRONT BUMPER.	\$ <del>900.00</del> 550	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
<b>TOTAL LABOUR CHARGES</b>		<b>: <u>\$ 2,422.00</u></b>	

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 1307 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 FRONT BUMPER <i>Repis</i>		\$	1,842.00	*
2 FRONT BUMPER FIXING PARTS <i>men</i>		\$	185.00	*
3 FRONT BUMPER GRILLE - CENTRE <i>men</i>		\$	159.00	*
4 RADIATOR GRILLE <i>could</i>		\$	1,406.00	✓
5 RADIATOR GRILLE CLOSING ELEMENT ?		\$	189.00	?
6 FRONT BUMPER COVER <i>men</i>		\$	121.00	*
7 FRONT BUMPER FOAM FILLER PIECE <i>men</i>		\$	187.00	*
8 FRONT REINFORCEMENT BEAM		\$	715.00	*
9 AIRCON STICKER <i>men</i>	NEC	\$	8.00	*
10 CAUTION SIGN STICKER <i>men</i>	NEC	\$	14.00	*
11 FRONT NO PLATE <i>dent</i>	S/N	\$	60.00	✓
12 SUNDRIES ?		\$	300.00	?
<b>TOTAL SPARE PARTS</b>	:	\$	<b>5,186.00</b>	
<b>TOTAL LABOUR CHARGES</b>	:	\$	<b>2,422.00</b>	
<b>GRAND TOTAL</b>	:	\$	<b>7,608.00</b>	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

 **PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*  
SURVEYED DATE : *05/10/20*  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : *Not Authorized, 03 days.*

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT