

TOYOTA

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg
Toyota Bodycafe Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

ESTIMATE

No : 196700086Z
No : MR-8500000-9

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

THIRD PARTY CLAIM	Account Detail	Account No S1000020 / TPCLAIM	Customer Detail
		Document No 0	M/S Grab Rentals Pte Ltd 6 Shenton Way #38-01 Oue Downtown Singapore 068809
		Document Date 01/10/2020	Work: 65703925

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	AHXEBW	Q1	29/09/2016	SLG4320X	0	56851	84/tp/SLG4320X
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDKB3FU003535195	2ZRR950900	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-RES2 TO SPRAY PAINT ON DAMAGED AFFECTED R/R PORTION OF CAR.				1180 2360.00
10	1	U52159-47913 COVER, RR BUMPER <i>see</i>	1.00	442.60		442.60
11	2	U52575-47040 RETAINER, RR BUMPER <i>see</i>	1.00	117.70		117.70
12	3	U52565-47900 FILLER, RR BUMPER <i>?</i>	1.00	123.70		123.70
13	4	U52453-47010 GUARD, RR BUMPER, <i>?</i>	1.00	576.30		576.30
14	5	U52591-47050 SEAL, RR BUMPER <i>?</i>	1.00	88.50		88.50
15	6	S52161-0K040 PIECE, RR BUMPER <i>see</i>	10.00	4.10		41.00
16	7	U61601-47150 PANEL SUB-ASSY, <i>see</i>	1.00	871.50		871.50
17	8	T08826-08115 PANEL BONDING AD <i>see</i>	1.00	267.20		267.20
18	9	U68123-47030 GLASS, RR DOOR <i>see photo?</i>	1.00	108.10		108.10
19	0	U68188-47030 WEATHERSTRIP, RR <i>see</i>	1.00	49.30		49.30
20	1	U21000-20 SIKA 182010 SIKA TACK GO! (BLA <i>see</i>	1.00	108.00		108.00
21	2	U21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>see</i>	1.00	200.00		200.00
22	3	U81581-47011 LENS & BODY, RR <i>?</i>	1.00	502.00		502.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

Reserv
4p for 100%
(days)
08/10/2020
Reserv before paint

For on behalf of Borneo Motors Consultants hence notify	Customer's Signature	Change Summary	Total	11,840.90
the Repairer of the following:	I hereby acknowledge receipt of vehicle	Parts	GST 7.00%	828.86
• To resurvey before/after spray painting		Labour	Less	0.00
• To display damaged part(s) during resurvey		Materials		
• Parts prices are subject to confirmation		Lubrication/Fluid		
• Third party survey is on a "Without Prejudice" basis		Others		
• No illegal modification(s) is allowed			Amount Due	12,669.76
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				

Acknowledged by Repairer

PLEASE TEAR ALONG PERFORATED LINE

4298550

TO SECURITY GUARD

Signature:
Date:

DATE 01/10/2020
TIME 15:42

4298550

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLG4320X

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

TOYOTA TIP CLAIM

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

: 196700086Z
No : MR-8500000-9

ESTIMATE

Read "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd 6 Shenton Way #38-01 Oue Downtown Singapore 068809 Work: 65703925
		Document No	
		0	
		Document Date	
		01/10/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	AHXEBW	Q1	ZVW50R	29/09/2016	SLG4320X	0	56851 84/tp/SLG4320X
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDKB3FU003535195	2ZRR950900	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				36 500
2	B	BP-LAB2 TO CHECK WIRING, LIGHTING AND CARRY OUT W ATERLEAK TEST.				122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
4	B	BP-LAB2 TO DRILL HOLE AND RE-INSTALL REAR SENSOR				180.00
5	B	BP-LAB2 TO REMOVE AND RE-INSTALL REAR SEAT, SIDE TRIM AND UPHOLSTERY TO ENABLE REPAIR.				720.00
6	B	BP-LAB2 TO REMOVE AND RE-INSTALL R/R QUATER PANEL GLASS TO ENABLE REPAIR.				282.60
7	B	BP-MECH2 TO CARRY OUT WHEEL ALIGNMENT CHECK.				180.00
8	B	BP-LAB2 TO REMOVE ALL NECESSARY DAMAGED PARTS, RE PLACE AND REPAIR R/R QUATER PANEL, REAR BUNMPER AND AFFECTED R/R PORTION OF CAR.				3600 4320.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4298549

4298549

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 01/10/2020
TIME 15:42

VEHICLE NO SLG4320X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors