

TOYOTA

Phone : 196700086Z
Fax No : MR-8500000-9

ESTIMATE

Read "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd
	Document No	6 Shenton Way
	0	#38-01 Oue Downtown
	Document Date	Singapore 068809
	01/10/2020	Work: 65703925

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	AHXEBW Q1	ZVW50R	29/09/2016	SLG4320X	0	56851	84/tp/SLG4320X
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDKB3FU003535195	2ZRR950900	60	Joe Tan Joo Seng	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-RES2 TO SPRAY PAINT ON DAMAGED AFFECTED R/R PORTION OF CAR.				1180 2360.00
10	1	U52159-47913 COVER, RR BUMPER <i>see</i>	1.00	442.60		442.60
11	2	U52575-47040 RETAINER, RR BUMPER <i>see</i>	1.00	117.70		117.70
12	3	U52565-47900 FILLER, RR BUMPER <i>? xsv</i>	1.00	123.70		123.70
13	4	U52453-47010 GUARD, RR BUMPER, <i>? xsv</i>	1.00	576.30		576.30
14	5	U52591-47050 SEAL, RR BUMPER <i>? xsv</i>	1.00	88.50		88.50
15	6	S52161-0K040 PIECE, RR BUMPER <i>see</i>	10.00	4.10		41.00
16	7	U61601-47150 PANEL SUB-ASSY, <i>see</i>	1.00	871.50		871.50
17	8	T08826-08115 PANEL BONDING AD <i>see</i>	1.00	267.20		267.20
18	9	U68123-47030 GLASS, RR DOOR <i>see X photo? xsv</i>	1.00	108.10		108.10
19	0	U68188-47030 WEATHERSTRIP, RR <i>see xsv</i>	1.00	49.30		49.30
20	1	U21000-20 SIKA 182010 SIKA TACK GO! (BLA <i>see</i>	1.00	108.00		108.00
21	2	U21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>see</i>	1.00	200.00		200.00
22	3	U81581-47011 LENS & BODY, RR <i>? xsv</i>	1.00	502.00		502.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of	Customer's Signature	Change Summary	Total
Borneo Motors Consultants hence notify the Repairer of the following:	Please acknowledge receipt of vehicle	Parts 3,495.90	11,840.90
• To resurvey before/after spray painting		Labour 8,345.00	GST 7.00%
• To display damaged part(s) during resurvey		Materials 0.00	828.86
• Parts prices are subject to confirmation		Lubrication/Fluid 0.00	Less 0.00
• Third party survey is on a "Without Prejudice" basis		Others 0.00	
• No illegal modification(s) is allowed			Amount Due 12,669.76
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			

Acknowledged by Repairer	PLEASE TEAR ALONG PERFORATED LINE	4298550
Signature:		4298550
Date:	DATE 01/10/2020	
	TIME 15:42	

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLG4320X

STOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

TOYOTA

TIP CLAIM

196700086Z
MR-8500000-9

ESTIMATE

My Toyota SG app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd 6 Shenton Way #38-01 One Downtown Singapore 068809 Work: 65703925
	Document No	
	0	
	Document Date	
	01/10/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	AHXEBW	Q1	29/09/2016	SLG4320X	0	56851	84/tp/SLG4320X
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDKB3FU003535195	2ZRR950900	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				36 50
2	B	BP-LAB2 TO CHECK WIRING, LIGHTING AND CARRY OUT W ATERLEAK TEST.				122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
4	B	BP-LAB2 TO DRILL HOLE AND RE-INSTALL REAR SENSOR				180.00
5	B	BP-LAB2 TO REMOVE AND RE-INSTALL REAR SEAT, SIDE TRIM AND UPHOLSTERY TO ENABLE REPAIR.				720.00
6	B	BP-LAB2 TO REMOVE AND RE-INSTALL R/R QUATER PANEL GLASS TO ENABLE REPAIR.				282.60
7	B	BP-MECH2 TO CARRY OUT WHEEL ALIGNMENT CHECK.				180.00
8	B	BP-LAB2 TO REMOVE ALL NECESSARY DAMAGED PARTS, RE PLACE AND REPAIR R/R QUATER PANEL, REAR BUMPER AND AFFECTED R/R PORTION OF CAR.				3600 4320.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4298549

SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 01/10/2020
TIME 15:42

4298549

VEHICLE NO SIG4320X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape