

08/11/13) wcf

ASS. REC. BY: Marcus

REF:

CS/CT/20010637/4vd3

ASSIGNMENT

From:

Date:

Veh No:

FBN 5-4897

Yr Regn:

10/18

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

FBN 5-4897

Make:

Yamaha NMAX 155 c.c 155

at Workshop m/s

BHM

Colour

White

A/C:

Insured / Std / NI / NA

of

Sp. Reading

45141

T/Radio: Insured / Std / NI / NA

Insured:

PA 98346

Eng/No:

Policy No.

C/No:

MH3SG 431000008372

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

8500/-

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

1

days

Res.: Yes or No

Lum Sum:

151

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 3533

Tyre Size:

F:

110-70-13

R:

130-70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TIMSUN

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

22/9/20

D.O.I.

5/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/10/20 Confirmed P/L 168.80 with Raymond. (Red 233.20, 58%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 12/10/20-Typist

Days Of Repair: 1

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) ___ S + RS ___ SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format : Merimen

Lump Sum / I.B.I: (\$ 168.80)

TOTAL



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534

ATTN: CHINA TAIPING INSURANCE (S) PTE LTD

NO. : 36874

DATE : 22/09/2020
CLAIM NO. : 11621
POLICY NO. : MC/00833714

FROM : HASRIANAH

VEHICLE NO. : FBN5489T
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOARD FOOTREST RH P/N: 59589	REPLACE	1.00	\$52.00	52.00 X
2	COVER SIDE CENTRE RH (WHITE) P/N: 58117	REPLACE	1.00	\$30.00	30.00 X
3	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	2.00	\$63.00	126.00
4	MUDGUARD FRONT (WHITE) P/N: 58087	REPLACE	1.00	\$52.00	52.00
5	SPRAY LACQUER ON FRONT MUDGUARD	Spray	1.00	\$49.00	49.00
6	STICKER (CISCO) MUDGUARD FRONT P/N: 58618	REPLACE	1.00	\$37.00	37.00
7	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$56.00	56.00 X

SUB TOTAL

\$402.00

GST @ 7 %

\$28.14

GRAND TOTAL (SGD)

\$430.14

50% deposit required before ordering of parts

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

*36874 *

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Acknowledge & Accepted By

1-52
10%
46.80
168.80

bizSAFE₃





BAN HOCK HIN
Co., Pte Ltd

Co Reg No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 36874

- Rev. 1

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534
ATTN: MOTOR CLAIMS DEPT

DATE : 22/09/2020
CLAIM NO. : 11621
POLICY NO. : MC/00833714

FROM : HASRIANAH

VEHICLE NO. : FBN5489T
MAKE/MODEL : YAM / NMAX155 ABS

S/N	Description	Action	Qty	Unit Price	Amount
1	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$50.00	50.00
2	MUDGUARD FRONT (WHITE) P/N: 58087	REPLACE	1.00	\$52.00 Disc %: 10.00	46.80
3	SPRAY LACQUER ON FRONT MUDGUARD	Spray	1.00	\$35.00	35.00
4	STICKER (CISCO) MUDGUARD FRONT P/N: 58618	REPLACE	1.00	\$37.00	37.00
SUB TOTAL					\$168.80
GST @ 7 %					\$11.82
GRAND TOTAL (SGD)					\$180.62

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*36874 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2022-14383
ISO 9001: 2015