



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20010639/Uvd3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 12-10-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 7115D	Veh. Inspected	SKV 5459G
Policy No.	D20MTPV01005393	Coverage (\$)	0.00
Claim No.	CMTD2002893/MYE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	05/10/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI TL TUCSON (A)	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHJ3813MGU072127	Colour	WHITE
Odometer	94106	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R18	ROADSTONE	6 mm
L/H Front Tyre	225/55 R18	ROADSTONE	6 mm
R/H Rear Tyre	225/55 R18	ROADSTONE	6 mm
L/H Rear Tyre	225/55 R18	ROADSTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/10/2020	Inspection Date	05/10/2020
Survey held at	15 KAKI BUKIT ROAD 4# 01-05/53		
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
--	-----------------------