

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SKV54596*at Workshop m/s *Asig motor*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *\$58k.*

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: *3* days

Res.: Yes or No

Lum Sum: *20* %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

UTA 46932

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: *SKV54596*Yr Regn: *9, 15*Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CAI*Make: *Hyundai T2 TUCSON**c.c. 1999*Colour: *white*

A/C: Insured / Std / NI / NA

Sp.Reading: *94106*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *KMHJ3813M64.072127*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *Good* / Jammed / Leaked / Burnt orBrake: *Good* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: *F: 225/55 R18*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *roadstone*Front: *6*Rear: *6*R/Bal. *6* mmR/Bal. *6* mmL/Bal. *6* mmL/Bal. *6* mmD.O.A. *2/10/20*D.O.I. *5/10/20*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision. *Rear*

Date / Time

Action / Instruction

*Rep 10k. N44 11068
Tailgate 1722.30**8/10/20 Confirmed 4/5 \$3300 with AH long (Red 6377.60, 66%)*

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 8/10/20-Typist

Days Of Repair: *3*Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) *S+RS* \$☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format : *TP*Lump Sum H.B. (\$) *3300*

TOTAL

Vehicle No. SKV5459G Hyundai Tucson

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR
	<u>PARTS (LIST ITEMS)</u>			
1	Rear bumper <i>De/To.in</i>		1100.00	<i>542.60</i>
2	Rear bumper RHS & LHS retainer@110	<i>11</i>	220.00	<i>X</i>
1	Rear bumper lower garnish	<i>CW7</i>	520.00	<i>393.20</i>
2	Rear bumper RHS & LHS reflector@122	<i>11</i>	244.00	<i>X</i>
1	Rear bumper reinforcement	<i>CNE</i>	650.00	<i>475.20</i>
1	Rear end panel	<i>R</i>	850.00	<i>X</i>
1	Rear tailgate	<i>SD</i>	1050.00	<i>579.50</i>
1	Rear tailgate number plate garnish	<i>De/To.in</i>	698.00	<i>X</i>
1	Rear tailgate chrome moulding	<i>11</i>	210.00	<i>X</i>
1	Rear exhaust pipe assy	<i>11</i>	980.00	<i>X</i>
			6522.00	
		less 20%	1304.40	20%
			5217.60	
	SPECIAL NETT ITEM			
1set	Rear bumper clips	<i>new</i>	60.00	<i>50</i>
2	Rear bumper reflector chrome@\$120	<i>11</i>	240.00	<i>X</i>
1	Rear windscreen moulding <i>Sealant</i>	<i>new</i>	180.00	<i>40</i>
1	Rear windscreen seal	<i>new</i>	80.00	<i>30</i>
2set	Rear reverse sensor @\$320	<i>shorts</i>	640.00	<i>200</i>
1	Rear tailgate Tucson emblem	<i>new</i>	85.00	<i>60</i>
1	Rear tailgate emblem <i>logo</i>	<i>new</i>	85.00	<i>52</i>
	Total Parts		6587.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Not Authorized

5/10/20
2/3 # 3300
3 days

Take photo after repair

1-3040.50
202
24324

Vehicle No. SKV5459G

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR
	LABOUR		
1	To remove the affected parts & fittings to commence repairs, replace damaged parts	1400.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	1000.00	650
3	To remove, refix wiring system at accident damaged areas and check for proper electrical function	150.00	30
4	To remove and refix rear tailgate component	120.00	60
5	To remove and refix rear windscreen	150.00	120
6	To remove and replace rear exhaust pipe	150.00 n1	X
7	To perform anti-rust treatment on affected areas	120.00	30
	Labour Total :	3090.00	
	TOTAL (PARTS & LABOUR):	9677.60	4864.40